



BUREAU  
VERITAS

# FACILITY CONDITION ASSESSMENT

prepared for

**Shelby County Board of Education**  
160 South Hollywood Street  
Memphis, Tennessee 38112-4892  
Michelle Stuart



Jackson Elementary School  
3925 Wales Avenue  
Memphis, Tennessee 38108

**PREPARED BY:**

Bureau Veritas  
6021 University Boulevard, Suite 200  
Ellicott City, Maryland 21043  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)

**BV CONTACT:**

Andy Hupp  
Program Manager  
800.733.0660 x7296632  
[Andy.Hupp@bureauveritas.com](mailto:Andy.Hupp@bureauveritas.com)

**BV PROJECT #:**

163745.23R000-021.354

**DATE OF REPORT:**

July 26, 2024

**ON SITE DATE:**

May 20, 2024

**Bureau Veritas**

6021 University Boulevard, Suite 200 | Ellicott City, Maryland 21043 | [www.us.bureauveritas.com](http://www.us.bureauveritas.com) | p 800.733.0660

## TABLE OF CONTENTS

<b>1. Executive Summary .....</b>	<b>1</b>
Campus Overview and Assessment Details .....	1
Campus Findings and Deficiencies .....	2
Facility Condition Index (FCI) .....	3
Immediate Needs.....	6
Key Findings .....	7
Plan Types.....	9
<b>2. Main Building .....</b>	<b>10</b>
<b>3. Annex.....</b>	<b>12</b>
<b>4. Site Summary.....</b>	<b>14</b>
<b>5. Property Space Use and Observed Areas .....</b>	<b>15</b>
<b>6. ADA Accessibility .....</b>	<b>16</b>
<b>7. Purpose and Scope .....</b>	<b>17</b>
<b>8. Opinions of Probable Costs .....</b>	<b>19</b>
Methodology .....	19
Definitions .....	19
<b>9. Certification.....</b>	<b>21</b>
<b>10. Appendices .....</b>	<b>22</b>



## 1. Executive Summary

### Campus Overview and Assessment Details

General Information	
<b>Property Type</b>	Elementary school
<b>Number of Buildings</b>	2
<b>Main Address</b>	3925 Wales Avenue, Memphis, Tennessee 38108
<b>Site Developed</b>	1957, Phase I / 1993 Phase II
<b>Site Area</b>	17.53 acres (estimated)
<b>Parking Spaces</b>	53 total spaces all in open lots; 3 of which are accessible.
<b>Outside Occupants/Leased Spaces</b>	None
<b>Date(s) of Visit</b>	May 20, 2024
<b>Management Point of Contact</b>	Ms. Mary Taylor, Shelby County Board of Education (901) 416-5376 <a href="mailto:taylorm15@scsk12.org">taylorm15@scsk12.org</a>
<b>On-site Point of Contact (POC)</b>	Mrs. Cox
<b>Assessment and Report Prepared By</b>	Dalton W Bryan
<b>Reviewed By</b>	AI Diefert Technical Report Reviewer For Andy Hupp Program Manager <a href="mailto:Andy.Hupp@bureauveritas.com">Andy.Hupp@bureauveritas.com</a> 800.733.0660 x7296632
<b>AssetCalc Link</b>	Full dataset for this assessment can be found at: <a href="https://www.assetcalc.net/">https://www.assetcalc.net/</a>

## Campus Findings and Deficiencies

### Historical Summary

This Elementary School was originally constructed in 1957 and the Annex building was added in 1993. There were no significant findings to suggest any widespread renovations since 1993.

### Architectural

Main Building: The building façade is a brick veneer, which has significant wear and needs repointing. Glazing is typical with aluminum windows and entrance doors are standard steel. The roofs are flat, and no leaks were reported. There are numerous condensation issues within the cafeteria area as evidenced by the hard tiles falling from the ceiling.

Annex: The construction of this building is the same as the main building with no issues found during the assessment.

### Mechanical, Electrical, Plumbing and Fire (MEPF)

Main Building: There have been significant upgrades to all the systems since the date of construction. From 1993 to 2018, most of these renovations have been to the HVAC and Electrical systems. No sprinkler systems: however, there are fire extinguishers and a fire panel serving both buildings.

Annex: All systems for this building are approaching five years old and will not require more than maintenance for the next several years. This building does have a sprinkler system.

### Site

This site is primarily grass with an upper and lower elevation connected by a central set of concrete stairs. There is a small playground between the two buildings and no significant landscaping. Parking lots are asphalt with typical wear and need usual maintenance and repairs.

### Recommended Additional Studies

No additional studies recommended at this time.

## Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.

### FCI Ranges and Description

<b>0 – 5%</b>	In new or well-maintained condition, with little or no visual evidence of wear or deficiencies.
<b>5 – 10%</b>	Subjected to wear but is still in a serviceable and functioning condition.
<b>10 – 30%</b>	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.
<b>30% and above</b>	Has reached the end of its useful or serviceable life. Renewal is now necessary.

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCIs have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

Facility (year built)	Cost/SF	Total SF	Replacement Value	Current	3-Year	5-Year	10-Year
Jackson Elementary School / Annex (2019)	\$400	9,704	\$3,881,600	0.0%	0.0%	2.4%	3.9%
Jackson Elementary School / Main Building (1957)	\$400	49,217	\$19,686,800	2.1%	2.6%	16.7%	27.2%

## Campus Level FCI:

The vertical bars below represent the year-by-year needs identified for the entire campus. The orange line in the graph below forecasts what would happen to the campus FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year (blue bars) are associated with the values along the right Y axis.


## Needs by Year with Unaddressed FCI Over Time

## FCI Analysis: Jackson Elementary School

Replacement Value: \$23,568,400

Inflation Rate: 3.0%

Average Needs per Year: \$513,700



The table below shows the anticipated costs by trade or building system over the next 20 years.

Systems Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
Facade	\$330,000	-	\$1,400	\$547,000	\$15,800	\$894,100
Roofing	-	-	-	\$576,900	\$269,400	\$846,200
Interiors	\$84,000	\$31,800	\$1,251,600	\$50,400	\$844,600	\$2,262,500
Plumbing	-	\$13,200	\$1,247,500	\$18,500	\$4,400	\$1,283,500
HVAC	-	-	\$2,800	\$591,300	\$416,200	\$1,010,300
Fire Protection	-	-	-	\$400	\$500	\$900
Electrical	-	\$40,300	\$42,500	\$338,600	\$657,400	\$1,078,800
Fire Alarm & Electronic Systems	-	-	\$204,900	-	-	\$204,900
Equipment & Furnishings	-	-	\$133,000	-	\$195,100	\$328,000
Site Pavement	\$11,800	\$86,500	\$12,500	\$14,500	\$36,300	\$161,700
Site Development	\$5,700	-	\$6,300	\$7,300	\$161,800	\$181,000
<b>TOTALS (3% inflation)</b>	<b>\$431,500</b>	<b>\$171,800</b>	<b>\$2,902,400</b>	<b>\$2,144,800</b>	<b>\$2,601,400</b>	<b>\$8,251,900</b>

\*Totals have been rounded to the nearest \$100.

## Immediate Needs

Facility/Building	Total Items	Total Cost
Jackson Elementary School / Main Building	2	\$414,000
Jackson Elementary School / Site	4	\$17,500
<b>Total</b>	<b>6</b>	<b>\$431,500</b>


## Main Building

ID	Location	Location Description	UF Code	Description	Condition	Plan Type	Cost
7638849	Jackson Elementary School / Main Building	Building Exterior	B2010	Exterior Walls, Brick, Repair/Repoint	Poor	Performance/Integrity	\$330,000
7651493	Jackson Elementary School / Main Building	Cafeteria	C1070	Suspended Ceilings, Hard Tile, ACM Abatement & Replacement w/ ACT, Replace	Poor	Performance/Integrity	\$84,000
<b>Total (2 items)</b>							<b>\$414,000</b>

## Site

ID	Location	Location Description	UF Code	Description	Condition	Plan Type	Cost
7641733	Jackson Elementary School / Site	Site	G2020	Parking Lots, Pavement, Asphalt, Seal & Stripe	Poor	Performance/Integrity	\$10,800
7638861	Jackson Elementary School / Site	Site	G2030	Sidewalk, any pavement type, Sectional Repairs (per Man-Day), Repair	Poor	Performance/Integrity	\$1,000
7641728	Jackson Elementary School / Site	Site	G2050	Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe	Poor	Performance/Integrity	\$5,400
7638844	Jackson Elementary School / Site	Site	G2060	Retaining Wall, Brick/Stone, Repair	Failed	Performance/Integrity	\$300
<b>Total (4 items)</b>							<b>\$17,500</b>

## Key Findings

**Exterior Walls in Poor condition.**


Brick  
Main Building Jackson Elementary School  
Building Exterior  
Uniformat Code: B2010  
Recommendation: **Repair/Repoint in 2024**

Priority Score: **89.9**Plan Type:  
Performance/Integrity

Cost Estimate: \$330,000

**\$\$\$\$**

Majority of exterior walls require repointing. - AssetCALC ID: 7638849

**Sidewalk in Poor condition.**

any pavement type, Sectional Repairs (per  
Man-Day)  
Site Jackson Elementary School Site  
Uniformat Code: G2030  
Recommendation: **Repair in 2024**

Priority Score: **85.9**Plan Type:  
Performance/Integrity

Cost Estimate: \$1,000

**\$\$\$\$**

Several crack, repairs towing tread on stairs and small section replacement needed. - AssetCALC ID: 7638861

**Parking Lots in Poor condition.**

Pavement, Asphalt  
Site Jackson Elementary School Site  
Uniformat Code: G2020  
Recommendation: **Seal and Stripe in 2024**

Priority Score: **84.9**Plan Type:  
Performance/Integrity

Cost Estimate: \$10,800

**\$\$\$**

Seal is depleted and striping worn up to end of useful life expectancy. - AssetCALC ID: 7641733

**Parking Lots in Poor condition.**

Pavement, Asphalt  
Site Jackson Elementary School Site  
Uniformat Code: G2020  
Recommendation: **Mill and Overlay in 2025**

Priority Score: **84.8**Plan Type:  
Performance/Integrity

Cost Estimate: \$84,000

**\$\$\$**

Seal is depleted and striping worn up to end of useful life expectancy. - AssetCALC ID: 7647558



## Athletic Surfaces and Courts in Poor condition.

Basketball/General, Asphalt Pavement  
Site Jackson Elementary School Site

Uniformat Code: G2050  
Recommendation: **Seal and Stripe in 2024**

Priority Score: **82.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$5,400

**\$\$\$\$**

Severely worn asphalt and striping for play areas are not visible. - AssetCALC ID: 7641728



## Retaining Wall in Failed condition.

Brick/Stone  
Site Jackson Elementary School Site

Uniformat Code: G2060  
Recommendation: **Repair in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$300

**\$\$\$\$**

Planter boxes need brick work repair. - AssetCALC ID: 7638844



## Suspended Ceilings in Poor condition.

Hard Tile, ACM Abatement and Replacement with ACT  
Main Building Jackson Elementary School Cafeteria

Uniformat Code: C1070  
Recommendation: **Replace in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$84,000

**\$\$\$\$**

Water damage - AssetCALC ID: 7651493


## Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance.

### Plan Type Descriptions

<b>Safety</b>	■ An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
<b>Performance/Integrity</b>	■ Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
<b>Accessibility</b>	■ Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
<b>Environmental</b>	■ Improvements to air or water quality, including removal of hazardous materials from the building or site.
<b>Retrofit/Adaptation</b>	■ Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs.
<b>Lifecycle/Renewal</b>	■ Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

### Plan Type Distribution (by Cost)



## 2. Main Building



### Main Building: Systems Summary

<b>Constructed/Renovated</b>	1957/1993	
<b>Building/Group Size</b>	49,217 SF	
<b>Number of Stories</b>	2 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Structure</b>	Masonry bearing walls with metal roof deck supported by steel joists and concrete strip/wall footing foundation system	Good
<b>Façade</b>	Wall Finish: Brick Windows: Aluminum	Fair
<b>Roof</b>	Primary: Flat construction with single-ply TPO/PVC membrane Secondary: Flat construction with single-ply EPDM membrane	Fair
<b>Interiors</b>	Walls: Painted CMU Floors: VCT Ceilings: ACT	Fair
<b>Elevators</b>	Passenger: One hydraulic car serving all 2 floors	Good
<b>Plumbing</b>	Distribution: Copper and Galvanized iron supply and cast iron and PVC waste and venting Hot Water: Gas domestic boilers and water heaters Fixtures: Toilets, urinals, and sinks in all restrooms	Fair
<b>HVAC</b>	Central System: Boilers, chillers, and air handlers feeding hydronic radiators and cabinet terminal units. Non-Central System: Split-system heat pumps, Ductless split-systems Supplemental components: Make-up air unit	Fair

## Main Building: Systems Summary

<b>Fire Suppression</b>	Fire extinguishers and kitchen hood system	Good
<b>Electrical</b>	Source & Distribution: Main panel with copper wiring. Interior Lighting: LED, linear fluorescent Emergency Power: None	Fair
<b>Fire Alarm</b>	Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Good
<b>Equipment/Special</b>	Commercial kitchen equipment	Good
<b>Accessibility</b>	Presently it does not appear an accessibility study is needed for this building. See Appendix D.	
<b>Key Issues and Findings</b>	Brick repointing required.	

### 3. Annex



#### Annex: Systems Summary

<b>Constructed/Renovated</b>	2019	
<b>Building Size</b>	9,704 SF	
<b>Number of Stories</b>	1 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Structure</b>	Masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system	Good
<b>Façade</b>	Wall Finish: Brick Windows: Aluminum	Good
<b>Roof</b>	Flat construction with single-ply TPO/PVC membrane	Good
<b>Interiors</b>	Walls: Painted CMU Ceilings: ACT	Good
<b>Elevators</b>	None	--
<b>Plumbing</b>	Distribution: Copper supply and PVC waste and venting Hot Water: Electric water heaters with integral tank Fixtures: Toilets, urinals, and sinks in all restrooms	Good
<b>HVAC</b>	Non-Central System: Packaged units	Good

## Annex: Systems Summary

<b>Fire Suppression</b>	Wet-pipe sprinkler system and fire extinguishers	Good
<b>Electrical</b>	Source & Distribution: Main panel with copper wiring. Interior Lighting: LED Emergency Power: None	Good
<b>Fire Alarm</b>	Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Good
<b>Equipment/Special</b>	None	--
<b>Accessibility</b>	Presently it does not appear an accessibility study is needed for this building. See Appendix D.	
<b>Key Issues and Findings</b>	None observed at the time of assessment.	

## 4. Site Summary



### Site Information

System	Description	Condition
<b>Pavement/Flatwork</b>	Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs.	Fair
<b>Site Development</b>	Building-mounted signage; chain link fencing; wood-board fence dumpster enclosures Playgrounds and sports fields Limited amount of park benches, picnic tables, trash receptacles	Fair
<b>Landscaping and Topography</b>	Limited landscaping features including lawns, trees, bushes, and planters. Irrigation present Severe site slopes throughout along the center of the property running east to west.	Fair
<b>Utilities</b>	Municipal water and sewer Local utility-provided electric and natural gas	Good
<b>Site Lighting</b>	Building-mounted: LED	Fair
<b>Ancillary Structures</b>	None	--
<b>Accessibility</b>	Presently it does not appear an accessibility study is needed for the exterior site areas. See Appendix D.	
<b>Key Issues and Findings</b>	Asphalt pavement needs mill and overlay and striping	

## 5. Property Space Use and Observed Areas

### Areas Observed

The interior spaces were observed to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

### Key Spaces Not Observed

All key areas of the property were accessible and observed.

## 6. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities.
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the Matrix that are included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this particular assessment. A full measured ADA survey would be required to identify any and all specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance.
- Only a representative sample of areas was observed.
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance.
- Itemized costs for individual non-compliant items are not included in the dataset.
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance.

No information about complaints or pending litigation associated with potential accessibility issues was provided during the interview process.

No detailed follow-up accessibility studies are included as recommendations since no major or moderate issues were identified at any of the campus facilities. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.

## 7. Purpose and Scope

### Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

### Condition Ratings

<b>Excellent</b>	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
<b>Good</b>	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
<b>Fair</b>	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
<b>Poor</b>	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed, or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
<b>Failed</b>	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
<b>Not Applicable</b>	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

## Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

## 8. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall & Swift*, Bureau Veritas's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

### Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

### Definitions

#### Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with Safety or Performance/Integrity Plan Types, are considered Immediate Needs.

## Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning systems or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

## Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

## Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short-Term window but will not be pushed 'irresponsibly' (too far) into the future.

## 9. Certification

Shelby County Board of Education (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Jackson Elementary School, 3925 Wales Avenue, Memphis, Tennessee 38108, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

**Prepared by:** Dalton W Bryan,  
Project Assessor

**Reviewed by:**   
Al Diefert,  
Technical Report Reviewer for  
Andy Hupp,  
Program Manager  
[Andy.Hupp@bureauveritas.com](mailto:Andy.Hupp@bureauveritas.com)  
800.733.0660 x-7296632 p

## 10. Appendices

---

- Appendix A: Photographic Record
- Appendix B: Site Plan
- Appendix C: Pre-Survey Questionnaire
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

---

## **Appendix A:** **Photographic Record**

---



## Photographic Overview



1 - FRONT ELEVATION



2 - LEFT ELEVATION




3 - REAR ELEVATION



4 - RIGHT ELEVATION



5 - ROOFING



6 - INTERIOR LIGHTING SYSTEM

## Photographic Overview



7 - CHILLER



8 - AIR HANDLER



9 - MAKE-UP AIR UNIT



10 - SPLIT SYSTEM



11 - BOILER



12 - ELECTRICAL SYSTEM

## Photographic Overview



13 - ANNEX FRONT ELEVATION



14 - ANNEX RIGHT ELEVATION



15 - ANNEX REAR ELEVATION



16 - ANNEX LEFT ELEVATION



17 - ANNEX ROOFING



18 - ANNEX PACKAGED UNIT

## Photographic Overview



19 - ANNEX SPLIT SYSTEM




20 - ANNEX PLUMBING SYSTEM




21 - ANNEX WATER HEATER



22 - ANNEX ELECTRICAL SYSTEM



23 - ANNEX INTERIOR LIGHTING SYSTEM



24 - ANNEX FIRE SUPPRESSION SYSTEM

## Photographic Overview



25 - FLAGPOLE



26 - PARKING LOTS



27 - FENCES & GATES



28 - DUMPSTER ENCLOSURE



29 - PLAYGROUND



30 - SITE STAIRS/RAMPS/RAILS

---

## **Appendix B:**

### **Site Plan**



## Site Plan



Google Earth

Project Number	Project Name
163745.23R000-021.354	Jackson Elementary School
Source	On-Site Date
Google	May 20, 2024



BUREAU  
VERITAS



---

## **Appendix C:**

### Pre-Survey Questionnaire

---



## BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

**Building / Facility Name:** Jackson Elementary School

**Name of person completing form:** NA

**Title / Association w/ property:** NA

**Length of time associated w/ property:** NA

**Date Completed:** NA

**Phone Number:** NA

**Method of Completion:** INCOMPLETE - client/POC unable to complete

---

The Pre-Survey Questionnaire was not filled out either prior to or during the assessment.

---

## **Appendix D:** Accessibility Review and Photos

---



**Visual Checklist - 2010 ADA Standards for Accessible Design****Property Name:** Jackson Elementary School**BV Project Number:** 163745.23R000-021.354

Abbreviated Accessibility Checklist					
Facility History & Interview					
	Question	Yes	No	Unk	Comments
<b>1</b>	Has an accessibility study been previously performed? If so, when?			<b>X</b>	
<b>2</b>	Have any ADA improvements been made to the property since original construction? Describe.			<b>X</b>	
<b>3</b>	Has building management reported any accessibility-based complaints or litigation?			<b>X</b>	

## Abbreviated Accessibility Checklist

## Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



CLOSE-UP OF STALL

Question		Yes	No	NA	Comments
1	Does the required number of standard ADA designated spaces appear to be provided ?	✗			
2	Does the required number of van-accessible designated spaces appear to be provided ?	✗			
3	Are accessible spaces on the shortest accessible route to an accessible building entrance ?	✗			
4	Does parking signage include the International Symbol of Accessibility ?	✗			
5	Does each accessible space have an adjacent access aisle ?	✗			
6	Do parking spaces and access aisles appear to be relatively level and without obstruction ?	✗			

## Abbreviated Accessibility Checklist

## Exterior Accessible Route



ACCESSIBLE PATH



ACCESSIBLE PATH

Question		Yes	No	NA	Comments
1	Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ?	✗			
2	Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ?	✗			
3	Are curb ramps present at transitions through raised curbs on all accessible routes?	✗			
4	Do curb ramps appear to have compliant slopes for all components ?	✗			
5	Do ramp runs on an accessible route appear to have compliant slopes ?	✗			
6	Do ramp runs on an accessible route appear to have a compliant rise and width ?	✗			

7	Do ramps on an accessible route appear to have compliant end and intermediate landings ?	X			
8	Do ramps and stairs on an accessible route appear to have compliant handrails?	X			
9	For stairways that are open underneath, are permanent barriers present that prevent or discourage access?			X	

## Abbreviated Accessibility Checklist

## Building Entrances



ACCESSIBLE ENTRANCE



DOOR HARDWARE

Question		Yes	No	NA	Comments
1	Do a sufficient number of accessible entrances appear to be provided ?	✗			
2	If the main entrance is not accessible, is an alternate accessible entrance provided?	✗			
3	Is signage provided indicating the location of alternate accessible entrances ?	✗			
4	Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ?	✗			
5	Do doors at accessible entrances appear to have compliant hardware ?	✗			
6	Do doors at accessible entrances appear to have a compliant clear opening width ?	✗			

7	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ?	X			
8	Do thresholds at accessible entrances appear to have a compliant height ?	X			

## Abbreviated Accessibility Checklist

## Interior Accessible Route



ACCESSIBLE INTERIOR PATH



DOOR HARDWARE

Question		Yes	No	NA	Comments
1	Does an accessible route appear to connect all public areas inside the building ?	✗			
2	Do accessible routes appear free of obstructions and/or protruding objects ?	✗			
3	Do ramps on accessible routes appear to have compliant slopes ?	✗			
4	Do ramp runs on an accessible route appear to have a compliant rise and width ?	✗			
5	Do ramps on accessible routes appear to have compliant end and intermediate landings ?	✗			
6	Do ramps on accessible routes appear to have compliant handrails ?	✗			

7	Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ?	X			
8	Do public transaction areas have an accessible, lowered service counter section ?	X			
9	Do public telephones appear mounted with an accessible height and location ?			X	
10	Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ?	X			
11	Do doors at interior accessible routes appear to have compliant hardware ?	X			
12	Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ?	X			
13	Do doors on interior accessible routes appear to have a compliant clear opening width ?	X			

## Abbreviated Accessibility Checklist

## Public Restrooms



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

Question		Yes	No	NA	Comments
1	Do publicly accessible toilet rooms appear to have a minimum compliant floor area ?		✗		There are no assessable toilet stalls
2	Does the lavatory appear to be mounted at a compliant height and with compliant knee area ?	✗			
3	Does the lavatory faucet have compliant handles ?	✗			
4	Is the plumbing piping under lavatories configured to protect against contact ?		✗		No need protection for plumbing under sinks
5	Are grab bars provided at compliant locations around the toilet ?			✗	
6	Do toilet stall doors appear to provide the minimum compliant clear width ?			✗	

7	Do toilet stalls appear to provide the minimum compliant clear floor area ?			X	
8	Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ?			X	No assessable alterations have been made
9	Do accessories and mirrors appear to be mounted at a compliant height ?			X	No assessable alterations have been made

## Abbreviated Accessibility Checklist

## Playgrounds &amp; Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

Question		Yes	No	NA	Comments
<b>1</b>	Is there an accessible route to the play area / s?	✗			
<b>2</b>	Has the play area been reviewed for accessibility ?			✗	
<b>3</b>	Are publicly accessible swimming pools equipped with an entrance lift ?			✗	

---

## **Appendix E:** Component Condition Report



## Component Condition Report | Jackson Elementary School / Annex

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Facade</b>						
B2010	Building Exterior	Good	Exterior Walls, Brick Veneer		6,068 SF	45 7641718
B2020	Building Exterior	Good	Glazing, any type, by SF		1,600 SF	25 7641727
B2050	Building Exterior	Good	Exterior Door, Steel, Standard		4	35 7651559
B2050	Building Exterior	Good	Exterior Door, Steel, Standard		4	35 7641734
<b>Roofing</b>						
B3010	Roof	Good	Roofing, Single-Ply Membrane, TPO/PVC		10,170 SF	15 7641725
<b>Interiors</b>						
C1030	Throughout building	Good	Interior Door, Steel, Standard		8	35 7651561
C1030	Throughout building	Good	Interior Door, Steel, w/ Extensive Glazing		4	35 7651562
C1070	Throughout building	Good	Suspended Ceilings, Acoustical Tile (ACT)		8,000 SF	20 7651569
C2010	Throughout building	Fair	Wall Finishes, any surface, Prep & Paint		24,260 SF	5 7651563
C2030	Throughout building	Good	Flooring, Vinyl Tile (VCT)		7,504 SF	10 7651566
C2030	Restrooms	Good	Flooring, Ceramic Tile		1,200 SF	35 7651574
C2030	Mechanical room	Fair	Flooring, any surface, w/ Epoxy Coating, Prep & Paint		1,000 SF	5 7651560
C2050	Throughout building	Fair	Ceiling Finishes, any flat surface, Prep & Paint		1,200 SF	5 7651567
<b>Plumbing</b>						
D2010	Restrooms	Good	Toilet, Commercial Water Closet		8	25 7651573
D2010	Hallway	Good	Drinking Fountain, Wall-Mounted, Single-Level		1	10 7641714
D2010	Throughout building	Good	Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China		8	25 7651564
D2010	Utility closet	Good	Backflow Preventer, Domestic Water		1	25 7641719
D2010	Utility closet	Good	Water Heater, Electric, Residential		1	10 7641739
D2010	Restrooms	Good	Urinal, Standard		2	25 7651571
D2010	Utility closet	Good	Sink/Lavatory, Service Sink, Floor		1	30 7641735

## Component Condition Report | Jackson Elementary School / Annex

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2010	Throughout building	Good	Plumbing System, Supply & Sanitary, High Density (excludes fixtures)	9,704	SF	35 7641721
D2010	Throughout building	Good	Drinking Fountain, Wall-Mounted, Single-Level	1	10	7651570
<b>HVAC</b>						
D3030	Main roof	Good	Split System, Condensing Unit/Heat Pump	1	10	7641738
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641715
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641724
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641716
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641729
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641736
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641730
D3050	Roof	Good	Packaged Unit, RTU, Pad or Roof-Mounted	1	15	7641732
<b>Fire Protection</b>						
D4010	Throughout building	Good	Fire Suppression System, Full System Install/Retrofit, High Density/Complexity, Renovate	9,704	SF	35 7641713
D4030	Throughout building	Good	Fire Extinguisher, Type ABC, up to 20 LB	2	8	7651572
<b>Electrical</b>						
D5020	Utility closet	Good	Distribution Panel, 120/208 V	1	25	7641717
D5040	Building exterior	Good	Exterior Fixture w/ Lamp, any type, w/ LED Replacement	4	15	7641723
D5040	Throughout building	Good	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	9,704	SF	15 7641726
<b>Fire Alarm &amp; Electronic Systems</b>						
D7050	Throughout, fed frpm main building	Fair	Fire Alarm System, Full System Upgrade, Standard Addressable, Maintain	9,704	SF	5 7658838

## Component Condition Report | Jackson Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Facade</b>						
B2010	Building Exterior	Poor	Exterior Walls, Brick, Repair/Repaint	10,000	SF	0 7638849

## Component Condition Report | Jackson Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B2020	Building Exterior	Fair	Glazing, any type, by SF	7,400	SF	10
B2020	Cafeteria	Fair	Screens & Shutters, Rolling Security Shutter, 10 to 50 SF	1	5	7651532
B2050	Building Exterior	Fair	Exterior Door, Steel, Standard	19	11	7638839
<b>Roofing</b>						
B3010	Roof	Fair	Roofing, Single-Ply Membrane, EPDM	8,400	SF	10
B3010	Roof	Fair	Roofing, Single-Ply Membrane, TPO/PVC	19,814	SF	10
<b>Interiors</b>						
C1030	Throughout building	Fair	Door Hardware, School, per Door	75	2	7651494
C1030	Throughout building	Fair	Interior Door, Wood, Solid-Core	85	5	7651490
C1070	Throughout building	Fair	Suspended Ceilings, Acoustical Tile Fiberglass	38,217	SF	5
C1070	Cafeteria	Poor	Suspended Ceilings, Hard Tile, ACM Abatement & Replacement w/ ACT	6,000	SF	0
C2010	Throughout building	Fair	Wall Finishes, Ceramic Tile	15,000	SF	5
C2010	Throughout building	Fair	Wall Finishes, any surface, Prep & Paint	108,042	SF	5
C2030	Boiler room	Fair	Flooring, any surface, w/ Epoxy Coating, Prep & Paint	2,500	SF	5
C2030	Stage Platform	Fair	Flooring, Wood, Strip, Refinish	200	SF	5
C2030	Throughout building	Fair	Flooring, Vinyl Tile (VCT)	43,517	SF	5
C2030	Restrooms	Fair	Flooring, Quarry Tile	2,500	SF	5
C2030	Library	Fair	Flooring, Carpet, Commercial Standard	500	SF	5
C2050	Throughout building	Fair	Ceiling Finishes, any flat surface, Prep & Paint	5,000	SF	5
<b>Plumbing</b>						
D2010	Boiler room	Fair	Pump, Circulation, Domestic Water	1	3	7638832
D2010	Kitchen	Fair	Water Heater, Gas, Commercial (125 MBH)	1	2	7651492
D2010	Throughout building	Fair	Drinking Fountain, Wall-Mounted, Single-Level	5	8	7638859
D2010	Throughout building	Fair	Sink/Lavatory, Trough Style, Solid Surface	1	5	7651489
D2010	Restrooms	Fair	Toilet, Commercial Water Closet	40	5	7651524

## Component Condition Report | Jackson Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2010	Throughout	Fair	Plumbing System, Supply & Sanitary, High Density (includes fixtures)	49,216	SF	5 7658830
D2010	Restrooms	Fair	Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China	24	5	7651500
D2010	Boiler room	Fair	Sink/Lavatory, Service Sink, Wall-Hung	6	5	7651502
D2010	Throughout building	Good	Drinking Fountain, Wall-Mounted, Single-Level	4	10	7651522
<b>HVAC</b>						
D3020	Boiler room	Good	Boiler, Gas, HVAC	1	20	7638860
D3020	Throughout building	Fair	Radiator, Hydronic, Column/Cabinet Style (per EA)	22	8	7638847
D3020	Boiler room	Good	Boiler, Gas, HVAC, 1001 to 2000 MBH	1	20	7651517
D3030	Roof	Fair	Split System, Condensing Unit/Heat Pump	1	7	7638856
D3030	Throughout building	Fair	Unit Ventilator, 500 CFM	21	10	7638835
D3030	West elevation	Fair	Chiller, Air-Cooled	1	8	7638865
D3050	Cafeteria	Good	Air Handler, Interior AHU, Easy/Moderate Access	1	19	7638862
D3050	Cafeteria	Good	Air Handler, Interior AHU, Easy/Moderate Access	1	19	7638855
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	12	7638834
D3050	Cafeteria	Good	Air Handler, Interior AHU, Easy/Moderate Access	1	19	7638845
D3050	Cafeteria	Good	Air Handler, Interior AHU, Easy/Moderate Access	1	19	7638840
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	12	7638833
D3050	Roof	Fair	Make-Up Air Unit, MUA or MAU	1	8	7638866
D3050	Cafeteria	Good	Air Handler, Interior AHU, Easy/Moderate Access	1	19	7638850
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	5	7638858
<b>Electrical</b>						
D5020	Boiler room	Fair	Distribution Panel, 120/208 V	1	2	7651540
D5020	Electrical room	Fair	Switchboard, 120/208 V, 1000 AMP	1	15	7638857
D5020	Electrical room	Fair	Switchboard, 277/480 V, 1000 AMP	1	15	7638836
D5020	Electrical room	Fair	Secondary Transformer, Dry, Stepdown	1	4	7638852

## Component Condition Report | Jackson Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5020	Boiler room	Fair	Secondary Transformer, Dry, Stepdown	1	2	7651523
D5020	Boiler room	Fair	Switchboard, 120/208 V	1	11	7651535
D5020	Boiler room	Fair	Switchboard, 277/480 V, 1000 AMP	1	12	7651495
D5020	Electrical room	Fair	Distribution Panel, 120/208 V	1	3	7638838
D5030	Throughout building	Fair	Electrical System, Wiring & Switches, High Density/Complexity	49,217 SF	11	7638846
D5040	Throughout building	Fair	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	49,217 SF	10	7638853
D5040	Building exterior	Fair	Exterior Fixture w/ Lamp, any type, w/ LED Replacement	6	10	7638851
D5040	Building exterior	Fair	Exterior Fixture w/ Lamp, any type, w/ LED Replacement	4	8	7638843

## Fire Alarm &amp; Electronic Systems

D7050	Throughout	Fair	Fire Alarm System, Full System Upgrade, Standard Addressable, Maintain	49,217 SF	5	7658831
-------	------------	------	--	-----------	---	---------

## Equipment &amp; Furnishings

E1030	Kitchen	Fair	Commercial Kitchen, Refrigeration Line	1 LS	5	7651542
E1030	Kitchen	Fair	Sink/Lavatory, Commercial Kitchen, 3-Bowl	1	5	7651491
E1030	Kitchen	Fair	Commercial Kitchen, Cooking Line Primary	1 LS	5	7651498
E1030	Kitchen	Fair	Foodservice Equipment, Exhaust Hood, 8 to 10 LF	2	5	7651488
E1030	Kitchen	Fair	Sink/Lavatory, Commercial Kitchen, 2-Bowl	2	5	7651507
E1030	Kitchen	Fair	Commercial Kitchen, Service Line	1 LS	5	7651508
E1070	Cafeteria	Fair	Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour	600 SF	5	7651521

## Component Condition Report | Jackson Elementary School / Site

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Pedestrian Plazas &amp; Walkways</b>						
G2020	Site	Poor	Parking Lots, Pavement, Asphalt, Mill & Overlay	24,000 SF	1	7647558
G2020	Site	Poor	Parking Lots, Pavement, Asphalt, Seal & Stripe	24,000 SF	0	7641733
G2030	Site	Poor	Sidewalk, any pavement type, Sectional Repairs (per Man-Day), Repair	1	0	7638861

## Component Condition Report | Jackson Elementary School / Site

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Athletic, Recreational &amp; Playfield Areas</b>						
G2050	Site	Fair	Play Structure, Multipurpose, Small	1	12	7638863
G2050	Site	Poor	Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe	12,000 SF	0	7641728
<b>Sitework</b>						
G2060	Site	Fair	Fences & Gates, Fence, Chain Link 10'	50 LF	11	7638867
G2060	Site	Fair	Flagpole, Metal	1	15	7638842
G2060	Site	Good	Dumpster Enclosure, Gates, Wood/Metal, Replace/Install	1	15	7641737
G2060	Site	Fair	Fences & Gates, Fence, Chain Link 8'	3,500 LF	11	7638848
G2060	Site	Failed	Retaining Wall, Brick/Stone, Repair	20 SF	0	7638844

## **Appendix F:** Replacement Reserves

---





## Replacement Reserves Report

7/24/2024

Location	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	Total Escalated Estimate
Jackson Elementary School	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Jackson Elementary School / Annex	\$0	\$0	\$0	\$0	\$0	\$92,628	\$0	\$0	\$380	\$0	\$57,950	\$0	\$0	\$0	\$509,611	\$0	\$0	\$511	\$0	\$50,571		\$711,651
Jackson Elementary School / Main Building	\$414,000	\$0	\$85,296	\$11,583	\$33,765	\$2,745,697	\$0	\$8,732	\$381,298	\$0	\$1,674,685	\$357,503	\$93,530	\$0	\$0	\$484,081	\$0	\$0	\$4,426	\$131,513	\$771,544	\$7,197,654
Jackson Elementary School / Site	\$17,450	\$86,520	\$0	\$0	\$0	\$18,780	\$0	\$0	\$0	\$0	\$21,771	\$122,851	\$14,258	\$0	\$0	\$31,783	\$0	\$0	\$0	\$0	\$29,259	\$342,672
<b>Grand Total</b>	<b>\$431,450</b>	<b>\$86,520</b>	<b>\$85,296</b>	<b>\$11,583</b>	<b>\$33,765</b>	<b>\$2,857,106</b>	<b>\$0</b>	<b>\$8,732</b>	<b>\$381,678</b>	<b>\$0</b>	<b>\$1,754,406</b>	<b>\$480,354</b>	<b>\$107,788</b>	<b>\$0</b>	<b>\$0</b>	<b>\$1,025,474</b>	<b>\$0</b>	<b>\$0</b>	<b>\$4,937</b>	<b>\$131,513</b>	<b>\$851,374</b>	<b>\$8,251,976</b>

Jackson Elementary School

Jackson Elementary School / Annex

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	Deficiency Repair Estimate	
B3010	Roof	7641725	Roofing, Single-Ply Membrane, TPO/PVC, Replace	20	5	15	10170	SF	\$17.00	\$172,890																					\$172,890		
C1070	Throughout building	7651569	Suspended Ceilings, Acoustical Tile (ACT), Replace	25	5	20	8000	SF	\$3.50	\$28,000																					\$28,000		
C2010	Throughout building	7651563	Wall Finishes, any surface, Prep & Paint	10	5	5	24260	SF	\$1.50	\$36,390																					\$72,780		
C2030	Mechanical room	7651560	Flooring, any surface, w/ Epoxy Coating, Prep & Paint	10	5	5	1000	SF	\$12.00	\$12,000																					\$24,000		
C2030	Throughout building	7651566	Flooring, Vinyl Tile (VCT), Replace	15	5	10	7504	SF	\$5.00	\$37,520																					\$37,520		
C2050	Throughout building	7651567	Ceiling Finishes, any flat surface, Prep & Paint	10	5	5	1200	SF	\$2.00	\$2,400																					\$4,800		
D2010	Utility closet	7641739	Water Heater, Electric, Residential, Replace	15	5	10	1	EA	\$900.00	\$900																						\$900	
D2010	Throughout building	7651570	Drinking Fountain, Wall-Mounted, Single-Level, Replace	15	5	10	1	EA	\$1,200.00	\$1,200																						\$1,200	
D2010	Hallway	7641714	Drinking Fountain, Wall-Mounted, Single-Level, Replace	15	5	10	1	EA	\$1,200.00	\$1,200																						\$1,200	
D3030	Main roof	7641738	Split System, Condensing Unit/Heat Pump, Replace	15	5	10	1	EA	\$2,300.00	\$2,300																						\$2,300	
D3050	Roof	7641715	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641724	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641716	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641729	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641736	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641730	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D3050	Roof	7641732	Packaged Unit, RTU, Pad or Roof-Mounted, Replace	20	5	15	1	EA	\$7,500.00	\$7,500																						\$7,500	
D4030	Throughout building	7651572	Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	2	8	2	EA	\$150.00	\$300																						\$600	
D5040	Throughout building	7641726	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures, Replace	20	5	15	9704	SF	\$5.00	\$48,520																						\$48,520	
D5040	Building exterior	7641723	Exterior Fixture w/ Lamp, any type, w/ LED Replacement, Replace	20	5	15	4	EA	\$600.00	\$2,400																						\$2,400	
D7050	Throughout, fed from main building	7658838	Fire Alarm System, Full System Upgrade, Standard Addressable, Maintain	20	15	5	9704	SF	\$3.00	\$29,112																						\$29,112	
<b>Totals, Unescalated</b>												\$0	\$0	\$0	\$0	\$0	\$79,902	\$0	\$0	\$300	\$0	\$43,120	\$0	\$0	\$0	\$0	\$327,100	\$0	\$0	\$300	\$0	\$28,000	\$478,722
<b>Totals, Escalated (3.0% inflation, compounded annually)</b>												\$0	\$0	\$0	\$0	\$0	\$92,628	\$0	\$0	\$380	\$0	\$57,950	\$0	\$0	\$0	\$0	\$509,611	\$0	\$0	\$511	\$0	\$50,571	\$711,651

Jackson Elementary School / Main Building

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost \*	Subtotal	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038</



## Replacement Reserves Report

7/24/2024

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	Deficiency Repair Estimate
C2030	Restrooms	7651499	Flooring, Quarry Tile, Replace	50	45	5	2500	SF	\$26.00	\$65,000						\$65,000															\$65,000	
C2030	Stage Platform	7651497	Flooring, Wood, Strip, Refinish	10	5	5	200	SF	\$4.00	\$800						\$800															\$1,600	
C2030	Throughout building	7651503	Flooring, Vinyl Tile (VCT), Replace	15	10	5	43517	SF	\$5.00	\$217,585						\$217,585															\$217,585	\$435,170
C2030	Library	7651506	Flooring, Carpet, Commercial Standard, Replace	10	5	5	500	SF	\$7.50	\$3,750						\$3,750															\$7,500	
C2050	Throughout building	7651525	Ceiling Finishes, any flat surface, Prep & Paint	10	5	5	5000	SF	\$2.00	\$10,000						\$10,000															\$20,000	
D2010	Kitchen	7651492	Water Heater, Gas, Commercial (125 MBH), Replace	20	18	2	1	EA	\$12,400.00	\$12,400				\$12,400																\$12,400		
D2010	Boiler room	7638832	Pump, Circulation, Domestic Water, Replace	15	12	3	1	EA	\$2,600.00	\$2,600				\$2,600																\$2,600	\$5,200	
D2010	Throughout	7658830	Plumbing System, Supply & Sanitary, High Density (includes fixtures), Replace	40	35	5	49216	SF	\$20.00	\$984,320						\$984,320															\$984,320	
D2010	Throughout building	7651489	Sink/Lavatory, Trough Style, Solid Surface, Replace	30	25	5	1	EA	\$2,500.00	\$2,500						\$2,500															\$2,500	
D2010	Boiler room	7651502	Sink/Lavatory, Service Sink, Wall-Hung, Replace	35	30	5	6	EA	\$1,400.00	\$8,400						\$8,400															\$8,400	
D2010	Restrooms	7651524	Toilet, Commercial Water Closet, Replace	30	25	5	40	EA	\$1,300.00	\$52,000						\$52,000															\$52,000	
D2010	Restrooms	7651500	Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China, Replace	30	25	5	24	EA	\$1,100.00	\$26,400						\$26,400															\$26,400	
D2010	Throughout building	7638859	Drinking Fountain, Wall-Mounted, Single-Level, Replace	15	7	8	5	EA	\$1,200.00	\$6,000																				\$6,000		
D2010	Throughout building	7651522	Drinking Fountain, Wall-Mounted, Single-Level, Replace	15	5	10	4	EA	\$1,200.00	\$4,800																				\$4,800		
D3020	Boiler room	7651517	Boiler, Gas, HVAC, 1001 to 2000 MBH, Replace	30	10	20	1	EA	\$50,800.00	\$50,800																				\$50,800		
D3020	Boiler room	7638860	Boiler, Gas, HVAC, Replace	30	10	20	1	EA	\$50,800.00	\$50,800																				\$50,800		
D3020	Throughout building	7638847	Radiator, Hydronic, Column/Cabinet Style (per EA), Replace	30	22	8	22	EA	\$800.00	\$17,600																				\$17,600		
D3030	West elevation	7638865	Chiller, Air-Cooled, Replace	25	17	8	1	EA	\$240,000.00	\$240,000																				\$240,000		
D3030	Roof	7638856	Split System, Condensing Unit/Heat Pump, Replace	15	8	7	1	EA	\$7,100.00	\$7,100																				\$7,100		
D3030	Throughout building	7638835	Unit Ventilator, 500 CFM, Replace	20	10	10	21	EA	\$7,400.00	\$155,400																				\$155,400		
D3050	Boiler room	7638833	Pump, Distribution, HVAC Heating Water, Replace	25	13	12	1	EA	\$6,800.00	\$6,800																				\$6,800		
D3050	Boiler room	7638834	Pump, Distribution, HVAC Heating Water, Replace	25	13	12	1	EA	\$6,800.00	\$6,800																				\$6,800		
D3050	Roof	7638866	Make-Up Air Unit, MUA or MAU, Replace	20	12	8	1	EA	\$35,000.00	\$35,000																				\$35,000		
D3050	Cafeteria	7638862	Air Handler, Interior AHU, Easy/Moderate Access, Replace	25	6	19	1	EA	\$15,000.00	\$15,000																				\$15,000		
D3050	Cafeteria	7638855	Air Handler, Interior AHU, Easy/Moderate Access, Replace	25	6	19	1	EA	\$15,000.00	\$15,000																				\$15,000		
D3050	Cafeteria	7638845	Air Handler, Interior AHU, Easy/Moderate Access, Replace	25	6	19	1	EA	\$15,000.00	\$15,000																				\$15,000		
D3050	Cafeteria	7638840	Air Handler, Interior AHU, Easy/Moderate Access, Replace	25	6	19	1	EA	\$15,000.00	\$15,000																				\$15,000		
D3050	Cafeteria	7638850	Air Handler, Interior AHU, Easy/Moderate Access, Replace	25	6	19	1	EA	\$15,000.00	\$15,000																				\$15,000		
D3060	Roof	7638858	Exhaust Fan, Centrifugal, 16" Damper, Replace	25	20	5	1	EA	\$2,400.00	\$2,400																				\$2,400		
D5020	Boiler room	7651523	Secondary Transformer, Dry, Stepdown, Replace	30	28	2	1	EA	\$30,000.00	\$30,000				\$30,000																\$30,000		
D5020	Electrical room	7638852	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$30,000.00	\$30,000				\$30,000																\$30,000		
D5020	Boiler room	7651535	Switchboard, 120/208 V, Replace	40	29	11	1	EA	\$50,000.00	\$50,000																				\$50,000		
D5020	Boiler room	7651495	Switchboard, 277/480 V, 1000 AMP, Replace	40	28	12	1	EA	\$52,000.00	\$52,000																				\$52,000		
D5020	Electrical room	7638836	Switchboard, 277/480 V, 1000 AMP, Replace	40	25	15	1	EA	\$52,000.00	\$52,000																				\$52,000		
D5020	Electrical room	7638857	Switchboard, 120/208 V, 1000 AMP, Replace	40	25	15	1	EA	\$52,100.00	\$52,10																						



## Replacement Reserves Report

7/24/2024

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	Deficiency Repair Estimate	
<b>Totals, Escalated (3.0% inflation, compounded annually)</b>										\$414,000	\$0	\$85,296	\$11,583	\$33,765	\$2,745,697	\$0	\$8,732	\$381,298	\$0	\$1,674,685	\$357,503	\$93,530	\$0	\$0	\$484,081	\$0	\$0	\$4,426	\$131,513	\$771,544	\$7,197,654		
<b>Jackson Elementary School / Site</b>																																	
<b>Uniformat Code Location Description ID Cost Description</b>																														Deficiency Repair Estimate			
G2020	Site	7641733	Parking Lots, Pavement, Asphalt, Seal & Stripe	5	5	0	24000	SF	\$0.45	\$10,800	\$10,800						\$10,800					\$10,800									\$10,800	\$54,000	
G2020	Site	7647558	Parking Lots, Pavement, Asphalt, Mill & Overlay	25	24	1	24000	SF	\$3.50	\$84,000		\$84,000																				\$84,000	
G2030	Site	7638861	Sidewalk, any pavement type, Sectional Repairs (per Man-Day), Repair	0	0	0	1	EA	\$1,000.00	\$1,000	\$1,000																					\$1,000	
G2050	Site	7641728	Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe	5	5	0	12000	SF	\$0.45	\$5,400	\$5,400						\$5,400					\$5,400									\$5,400	\$27,000	
G2050	Site	7638863	Play Structure, Multipurpose, Small, Replace	20	8	12	1	EA	\$10,000.00	\$10,000													\$10,000										\$10,000
G2060	Site	7638848	Fences & Gates, Fence, Chain Link 8', Replace	40	29	11	3500	LF	\$25.00	\$87,500												\$87,500										\$87,500	
G2060	Site	7638867	Fences & Gates, Fence, Chain Link 10', Replace	40	29	11	50	LF	\$25.00	\$1,250											\$1,250										\$1,250		
G2060	Site	7638842	Flagpole, Metal, Replace	30	15	15	1	EA	\$2,500.00	\$2,500													\$2,500										\$2,500
G2060	Site	7638844	Retaining Wall, Brick/Stone, Repair	0	0	0	20	SF	\$12.50	\$250	\$250																						\$250
G2060	Site	7641737	Dumpster Enclosure, Gates, Wood/Metal, Replace/Install	20	5	15	1	EA	\$1,700.00	\$1,700													\$1,700										\$1,700
<b>Totals, Unescalated</b>											\$17,450	\$84,000	\$0	\$0	\$0	\$16,200	\$0	\$0	\$0	\$0	\$16,200	\$88,750	\$10,000	\$0	\$0	\$20,400	\$0	\$0	\$0	\$0	\$0	\$16,200	\$269,200
<b>Totals, Escalated (3.0% inflation, compounded annually)</b>											\$17,450	\$86,520	\$0	\$0	\$0	\$18,780	\$0	\$0	\$0	\$0	\$21,771	\$122,851	\$14,258	\$0	\$0	\$31,783	\$0	\$0	\$0	\$0	\$0	\$29,259	\$342,672

---

## **Appendix G:** Equipment Inventory List

---



D20 Plumbing													
Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7638832	D2010	Pump	Circulation, Domestic Water	.5 HP	Jackson Elementary School / Main Building	Boiler room	Balbor	33117	37B01X54	2001		
2	7641739	D2010	Water Heater	Electric, Residential	50 GAL	Jackson Elementary School / Annex	Utility closet	Bradford White	LE250S3-3NLWW	WC44843063	2019		
3	7651492	D2010	Water Heater	Gas, Commercial (125 MBH)	82 GAL	Jackson Elementary School / Main Building	Kitchen	Rheem / Ruud	G82-156	RNG 1000G05153	1998		
4	7641719	D2010	Backflow Preventer	Domestic Water	2 IN	Jackson Elementary School / Annex	Utility closet	Wilkins	975xl	ACA5218	2019		
D30 HVAC													
Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7638860	D3020	Boiler	Gas, HVAC	1500 MBH	Jackson Elementary School / Main Building	Boiler room	Lochinvar	PBN1501	C14H00261207	2014		
2	7651517	D3020	Boiler	Gas, HVAC, 1001 to 2000 MBH	1501 MBH	Jackson Elementary School / Main Building	Boiler room	Lochinvar	PBN1501	C14H00261206	2014		
3	7638847	D3020	Radiator	Hydronic, Column/Cabinet Style (per EA)		Jackson Elementary School / Main Building	Throughout building						22
4	7638865	D3030	Chiller	Air-Cooled	160 TON	Jackson Elementary School / Main Building	West elevation	Carrier	30R A1596-03-73	5107085200	2007		
5	7638856	D3030	Split System	Condensing Unit/Heat Pump	5 TON	Jackson Elementary School / Main Building	Roof	Lennox	SSB060H4S45G	5816H05494	2016		
6	7641738	D3030	Split System	Condensing Unit/Heat Pump	1 TON	Jackson Elementary School / Annex	Main roof	Daikin Industries	RX12NMVJU	Illegible	2019		

7	7638835	D3030	<b>Unit Ventilator</b>	500 CFM	500 CFM	Jackson Elementary School / Main Building	Throughout building	Daikin Industries	Inaccessible	Inaccessible	21
8	7638834	D3050	<b>Pump</b>	Distribution, HVAC Heating Water	10 HP	Jackson Elementary School / Main Building	Boiler room	U.S. Electrical Motors	E659A	X1X251R134M	2011
9	7638833	D3050	<b>Pump</b>	Distribution, HVAC Heating Water	10 HP	Jackson Elementary School / Main Building	Boiler room	U.S. Electrical Motors	E659A	X1X251R134M	2011
10	7638862	D3050	<b>Air Handler</b>	Interior AHU, Easy/Moderate Access	1600 CFM	Jackson Elementary School / Main Building	Cafeteria	Daikin Industries	Inaccessible	Inaccessible	2018
11	7638855	D3050	<b>Air Handler</b>	Interior AHU, Easy/Moderate Access	1600 CFM	Jackson Elementary School / Main Building	Cafeteria	Inaccessible	Inaccessible	Inaccessible	2018
12	7638845	D3050	<b>Air Handler</b>	Interior AHU, Easy/Moderate Access	1600 CFM	Jackson Elementary School / Main Building	Cafeteria	Daikin Industries	Inaccessible	Inaccessible	2018
13	7638840	D3050	<b>Air Handler</b>	Interior AHU, Easy/Moderate Access	1600 CFM	Jackson Elementary School / Main Building	Cafeteria	Daikin Industries	Inaccessible	Inaccessible	2018
14	7638850	D3050	<b>Air Handler</b>	Interior AHU, Easy/Moderate Access	1600 CFM	Jackson Elementary School / Main Building	Cafeteria	Daikin Industries	Inaccessible	Inaccessible	2018
15	7638866	D3050	<b>Make-Up Air Unit</b>	MUA or MAU	6000 CFM	Jackson Elementary School / Main Building	Roof	Illegible	Illegible	Illegible	
16	7641715	D3050	<b>Packaged Unit</b>	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05647	2019
17	7641724	D3050	<b>Packaged Unit</b>	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05649	2019
18	7641716	D3050	<b>Packaged Unit</b>	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05643	2019

19	7641729	D3050	Packaged Unit	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05641	2019
20	7641736	D3050	Packaged Unit	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05637	2019
21	7641730	D3050	Packaged Unit	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05634	2019
22	7641732	D3050	Packaged Unit	RTU, Pad or Roof-Mounted	3 TON	Jackson Elementary School / Annex	Roof	Lennox	LGH036H4EB5Y	5619M05631	2019
23	7638858	D3060	Exhaust Fan	Centrifugal, 16" Damper	2000 CFM	Jackson Elementary School / Main Building	Roof	ECON-AIR	Illegible	Illegible	

**D40 Fire Protection**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7651572	D4030	Fire Extinguisher	Type ABC, up to 20 LB		Jackson Elementary School / Annex	Throughout building				2019		2

**D50 Electrical**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7638852	D5020	Secondary Transformer	Dry, Stepdown	300 KVA	Jackson Elementary School / Main Building	Electrical room	Siemens	3F3Y300	No dataplate	1993		
2	7651523	D5020	Secondary Transformer	Dry, Stepdown	300 KVA	Jackson Elementary School / Main Building	Boiler room	Siemens	3F3Y300	No dataplate	1995		
3	7651535	D5020	Switchboard	120/208 V	800 AMP	Jackson Elementary School / Main Building	Boiler room	Siemens	Illegible	No dataplate	1995		
4	7638857	D5020	Switchboard	120/208 V, 1000 AMP	800 AMP	Jackson Elementary School / Main Building	Electrical room	Siemens	S4	No dataplate	1993		
5	7638836	D5020	Switchboard	277/480 V, 1000 AMP	1200 AMP	Jackson Elementary School / Main Building	Electrical room	Siemens	S4E60ML120EBS	18-86432-A00	1993		

6	7651495	D5020	<b>Switchboard</b>	277/480 V, 1000 AMP 1200 AMP	Jackson Elementary School / Main Building	Boiler room	Siemens	S4E60ML120EBS	18-86432-A00	1995
7	7651540	D5020	<b>Distribution Panel</b>	120/208 V 800 AMP	Jackson Elementary School / Main Building	Boiler room	Westinghouse	CDP 8PH 4w	D362062	1983
8	7641717	D5020	<b>Distribution Panel</b>	120/208 V 400 AMP	Jackson Elementary School / Annex	Utility closet	GE	AEF3604KBX	AXF187	2019
9	7638838	D5020	<b>Distribution Panel</b>	120/208 V 800 AMP	Jackson Elementary School / Main Building	Electrical room	Westinghouse	D 362062	HY 483365STX	1982

**E10 Equipment**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7651488	E1030	<b>Foodservice Equipment</b>	Exhaust Hood, 8 to 10 LF	Jackson Elementary School / Main Building	Kitchen	ECON-AIR	4824 EFG	NA	2014			2
2	7651507	E1030	<b>Sink/Lavatory</b>	Commercial Kitchen, 2-Bowl	Jackson Elementary School / Main Building	Kitchen				1957			2
3	7651491	E1030	<b>Sink/Lavatory</b>	Commercial Kitchen, 3-Bowl	Jackson Elementary School / Main Building	Kitchen				1957			