

FACILITY CONDITION ASSESSMENT

prepared for

Shelby County Board of Education
160 South Hollywood Street
Memphis, Tennessee 38112-4892
Michelle Stuart



Lucie E. Campbell Elementary School
3232 Birchfield Drive
Memphis, Tennessee 38127

PREPARED BY:

Bureau Veritas
6021 University Boulevard, Suite 200
Ellicott City, Maryland 21043
800.733.0660
www.us.bureauveritas.com

BV CONTACT:

Andy Hupp
Program Manager
800.733.0660 x7296632
Andy.Hupp@bureauveritas.com

BV PROJECT #:

163745.23R000-051.354

DATE OF REPORT:

April 19, 2024

ON SITE DATE:

December 11-12, 2023

Bureau Veritas

6021 University Boulevard, Suite 200 | Ellicott City, Maryland 21043 | www.us.bureauveritas.com | p 800.733.0660

TABLE OF CONTENTS

| | |
|---|-----------|
| 1. Executive Summary | 1 |
| Property Overview and Assessment Details | 1 |
| Significant/Systemic Findings and Deficiencies | 2 |
| Facility Condition Index (FCI) | 3 |
| Immediate Needs..... | 4 |
| Key Findings | 5 |
| Plan Types..... | 6 |
| 2. Building and Site Information | 8 |
| 3. Property Space Use and Observed Areas | 11 |
| 4. ADA Accessibility | 12 |
| 5. Purpose and Scope | 13 |
| 6. Opinions of Probable Costs | 15 |
| Methodology | 15 |
| Definitions | 15 |
| 7. Certification..... | 17 |
| 8. Appendices | 18 |

1. Executive Summary

Property Overview and Assessment Details

General Information

| | |
|--|---|
| Property Type | School |
| Main Address | 3232 Birchfield Drive, Memphis, Tennessee 38127 |
| Site Developed | 2003 |
| Site Area | 12.0 acres (estimated) |
| Parking Spaces | 245 total spaces all in open lots; 8 of which are accessible |
| Building Area | 84,740 SF |
| Number of Stories | Two above grade |
| Outside Occupants/Leased Spaces | None |
| Date(s) of Visit | December 11-12, 2023 |
| Management Point of Contact | Memphis-Shelby County Schools/Facility Planning/Property Management, Michelle Stuart, Director 901.830.8412 stuartml@scsk12.org |
| On-site Point of Contact (POC) | Christopher Johnson |
| Assessment and Report Prepared By | Patrick Fallon |
| Reviewed By | Al Diefert Technical Report Reviewer For Andy Hupp Program Manager Andy.Hupp@bureauveritas.com 800.733.0660 x7296632 |
| AssetCalc Link | Full dataset for this assessment can be found at: https://www.assetcalc.net/ |

Significant/Systemic Findings and Deficiencies

Historical Summary

Lucie E. Campbell Elementary School was built in 2003 and has had no major renovations or reconfigurations.

Architectural

The building exterior is a combination of brick and decorative CMU. There is some evidence that the CMU mortar joints have been addressed in the past and an allowance for repointing has been included in the asset listing.

The roof is a combination of flat TPO on the two-story center core building and pitched metal roof on the single story wings. The TPO is at the end of its useful life and has delaminated in several areas and needs spot repair or replacement.

Windows throughout have a protective security screen installed on both the first and second floors.

Interior floors are mostly VCT with carpet installed in some offices and in the library. The library is planned to receive faux wood plank vinyl flooring in the future. Ceilings are primarily an acoustic ceiling tile and grid system. Wall finishes are mostly paint. Normal useful life can be expected for interior finishes with most being in their final 20% of their expected life cycle.

Mechanical, Electrical, Plumbing and Fire (MEPF)

Air Handler Units on the 2-story center core and the Chiller were replaced in 2022. There are reports that the Chiller continues to need frequent resetting and that the older HVAC controls are not regulating the newer units correctly. Roof Top Units on the single story flat roof area (kitchen) were not replaced in 2022 and are nearing the end of their useful life.

Electrical systems seem original and their normal service life is expected. Lighting systems are mostly fluorescent lay in troffer fixtures with LED fixtures on the building exterior.

Plumbing systems mostly serve larger restrooms located at the intersection of the wings on the ground floor and in the center of the second floor as well as some smaller single restrooms distributed throughout the facility and the commercial kitchen.

The building is fully fire sprinkled and there is a chemical system on the kitchen range hood. The fire alarm system appears to be original and is at the end of its typical useful life.

Site

Site asphalt pavement is heavily weathered and cracked with potholes in several areas on the roadway which goes around the rear of the school. Pavement markings are also heavily weathered and worn. An allowance to mill and overlay the asphalt pavement has been included in the asset listing.

There are reports that the site lighting is inadequate along the rear roadway and in the main parking lots and there is a desire to upgrade the existing lighting as well as add additional lighting in these areas.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.

FCI Ranges and Description

| | |
|----------------------|---|
| 0 – 5% | In new or well-maintained condition, with little or no visual evidence of wear or deficiencies. |
| 5 – 10% | Subjected to wear but is still in a serviceable and functioning condition. |
| 10 – 30% | Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life. |
| 30% and above | Has reached the end of its useful or serviceable life. Renewal is now necessary. |

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

FCI Analysis | Lucie E. Campbell Elementary School(2003)

| Replacement Value \$ 33,896,000 | Total SF 84,740 | Cost/SF \$ 400 | Est Reserve Cost | FCI |
|------------------------------------|--------------------|-------------------|------------------|--------|
| Current | | \$ 49,300 | | 0.1 % |
| 3-Year | | \$ 4,250,200 | | 12.5 % |
| 5-Year | | \$ 4,765,700 | | 14.1 % |
| 10-Year | | \$ 6,178,300 | | 18.2 % |

The vertical bars below represent the year-by-year needs identified for the site. The orange line in the graph below forecasts what would happen to the FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year (blue bars) are associated with the values along the right Y axis.


Needs by Year with Unaddressed FCI Over Time

FCI Analysis: Lucie E. Campbell Elementary School

Replacement Value: \$33,896,000

Inflation Rate: 3.0%

Average Needs per Year: \$561,700



Immediate Needs

| Facility/Building | Total Items | Total Cost |
|-------------------------------------|-------------|-----------------|
| Lucie E. Campbell Elementary School | 4 | \$49,300 |
| Total | 4 | \$49,300 |

Lucie E. Campbell Elementary School

| ID | Location | Location Description | UF Code | Description | Condition | Plan Type | Cost |
|------------------------|-------------------------------------|----------------------|---------|---|-----------|-----------------------|-----------------|
| 7177828 | Lucie E. Campbell Elementary School | Building exterior | B2010 | Exterior Walls, Concrete Block (CMU), Repair/Repoint | Poor | Performance/Integrity | \$20,000 |
| 7168599 | Lucie E. Campbell Elementary School | Kitchen | E1030 | Foodservice Equipment, Refrigerator, Undercounter 1-Door, Replace | Failed | Performance/Integrity | \$1,100 |
| 7168683 | Lucie E. Campbell Elementary School | Kitchen | E1030 | Foodservice Equipment, Icemaker, Freestanding, Replace | Failed | Performance/Integrity | \$6,700 |
| 7168650 | Lucie E. Campbell Elementary School | Kitchen | E1030 | Foodservice Equipment, Dishwasher Commercial, Replace | Failed | Performance/Integrity | \$21,500 |
| Total (4 items) | | | | | | | \$49,300 |

Key Findings



Exterior Walls in Poor condition.

Concrete Block (CMU)

Lucie E. Campbell Elementary School Building exterior

Uniformat Code: B2010

Recommendation: **Repair/Repoint in 2023**

Priority Score: **88.9**

Plan Type:

Performance/Integrity

Cost Estimate: \$20,000

\$\$\$\$

Refresh and address previous repair areas - AssetCALC ID: 7177828



Parking Lots in Poor condition.

Pavement, Asphalt

Lucie E. Campbell Elementary School Site

Uniformat Code: G2020

Recommendation: **Mill and Overlay in 2025**

Priority Score: **84.8**

Plan Type:

Performance/Integrity

Cost Estimate: \$650,100

\$\$\$\$

Alligator cracking and potholes - AssetCALC ID: 7168627



Foodservice Equipment in Failed condition.

Icemaker, Freestanding

Lucie E. Campbell Elementary School Kitchen

Uniformat Code: E1030

Recommendation: **Replace in 2023**

Priority Score: **81.9**

Plan Type:

Performance/Integrity

Cost Estimate: \$6,700

\$\$\$\$

Not operating - AssetCALC ID: 7168683



Foodservice Equipment in Failed condition.

Dishwasher Commercial

Lucie E. Campbell Elementary School Kitchen

Uniformat Code: E1030

Recommendation: **Replace in 2023**

Priority Score: **81.9**

Plan Type:

Performance/Integrity

Cost Estimate: \$21,500

\$\$\$\$

Out of service - AssetCALC ID: 7168650



Foodservice Equipment in Failed condition.

Refrigerator, Undercounter 1-Door
 Lucie E. Campbell Elementary School Kitchen
 Uniformat Code: E1030
 Recommendation: **Replace in 2023**

Priority Score: **81.9**
 Plan Type:
 Performance/Integrity
 Cost Estimate: \$1,100
\$\$\$\$

Out of service - AssetCALC ID: 7168599



Site Walkway Fixture w/ Lamp in Poor condition.

Bollard Style
 Lucie E. Campbell Elementary School Site
 Uniformat Code: G4050
 Recommendation: **Replace/Install in 2024**

Priority Score: **81.9**
 Plan Type:
 Performance/Integrity
 Cost Estimate: \$9,100
\$\$\$\$

Some lights damaged and missing - AssetCALC ID: 7168625


Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance.

Plan Type Descriptions

| | |
|------------------------------|---|
| Safety | ■ An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. |
| Performance/Integrity | ■ Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability. |
| Accessibility | ■ Does not meet ADA, UFAS, and/or other accessibility requirements. |
| Environmental | ■ Improvements to air or water quality, including removal of hazardous materials from the building or site. |
| Retrofit/Adaptation | ■ Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs. |
| Lifecycle/Renewal | ■ Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted. |

Plan Type Distribution (by Cost)



2. Building and Site Information



Systems Summary

| System | Description | Condition |
|------------------|---|-----------|
| Structure | Masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system | Fair |
| Façade | Primary Wall Finish: Brick Secondary Wall Finish: CMU Windows: Aluminum | Fair |
| Roof | Primary: Gable construction with metal finish Secondary: Flat construction with single-ply TPO/PVC membrane | Fair |
| Interiors | Walls: Painted gypsum board Floors: Carpet, VCT Ceilings: ACT | Fair |
| Elevators | Passenger: One hydraulic cars serving all two floors | Fair |
| Plumbing | Distribution: Copper supply and PVC waste and venting Hot Water: Gas water heaters with integral tanks Fixtures: Toilets, urinals, and sinks in all restrooms | Fair |
| HVAC | Central System: Boilers and chillers feeding Air Handler Units Non-Central System: Roof Top Units and Split-system heat pumps | Fair |

Systems Summary

| | | |
|-----------------------------------|---|------|
| Fire Suppression | Wet-pipe sprinkler system with fire extinguishers and kitchen hood system | Fair |
| Electrical | Source and Distribution: Main switchboard with copper wiring Interior Lighting: Linear fluorescent Emergency Power: None | Fair |
| Fire Alarm | Alarm panel with smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs | Fair |
| Equipment/Special | Commercial kitchen equipment | Fair |
| Site Pavement | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs and ramps | Poor |
| Site Development | Building-mounted and Property entrance signage; chain link fencing; Playgrounds Limited park benches | Fair |
| Landscaping and Topography | Limited landscaping features including lawns, trees, bushes, and planters Irrigation not present Low to moderate site slopes throughout | Fair |
| Utilities | Municipal water and sewer Local utility-provided electric and natural gas | Fair |
| Site Lighting | Pole-mounted: LED Building-mounted: LED Pedestrian walkway lighting | Fair |
| Ancillary Structures | Storage sheds | Fair |
| Accessibility | Presently it does not appear an accessibility study is needed for this property. See Appendix D. | |
| Key Issues and Findings | Heavy asphalt wear with severe alligator cracking and potholes, inadequate site lighting. Out of service kitchen equipment | |

Systems Expenditure Forecast

| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
|---------------------------------|-----------------|------------------------|-----------------------|-----------------------|-------------------------|---------------------|
| Structure | - | - | - | - | - | - |
| Facade | \$20,000 | \$4,000 | \$44,300 | \$117,900 | \$134,200 | \$320,300 |
| Roofing | - | \$521,200 | - | - | \$1,361,800 | \$1,883,000 |
| Interiors | - | \$721,700 | \$336,800 | - | \$1,242,800 | \$2,301,200 |
| Conveying | - | \$14,900 | - | \$80,600 | \$14,900 | \$110,400 |
| Plumbing | - | \$48,700 | - | \$139,200 | \$1,686,000 | \$1,873,900 |
| HVAC | - | \$102,600 | \$46,800 | \$710,200 | \$1,560,500 | \$2,420,100 |
| Fire Protection | - | \$5,000 | \$105,100 | - | \$3,800 | \$113,900 |
| Electrical | - | \$410,200 | - | \$263,700 | \$570,900 | \$1,244,700 |
| Fire Alarm & Electronic Systems | - | \$1,215,000 | - | - | \$1,247,600 | \$2,462,600 |
| Equipment & Furnishings | \$29,300 | \$162,400 | \$11,000 | \$54,100 | \$213,300 | \$470,100 |
| Special Construction & Demo | - | - | - | \$3,400 | - | \$3,400 |
| Site Development | - | \$145,800 | \$15,800 | \$28,300 | \$269,800 | \$459,600 |
| Site Utilities | - | \$115,500 | - | \$15,300 | - | \$130,700 |
| Site Pavement | - | \$689,700 | - | - | - | \$689,700 |
| TOTALS (3% inflation) | \$49,300 | \$4,156,600 | \$559,700 | \$1,412,700 | \$8,305,500 | \$14,483,800 |

*Totals have been rounded to the nearest \$100.

3. Property Space Use and Observed Areas

Areas Observed

A representative sample of the interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed

Areas of note that were either inaccessible or not observed for other reasons are listed here:

- Multiple classrooms; classes in session

4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the tables that are included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this particular assessment. A full measured ADA survey would be required to identify any and all specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are not included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The facility was originally constructed in 2003. The facility has not since been substantially renovated.

No information about complaints or pending litigation associated with potential accessibility issues was provided during the interview process.

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.

5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

| Condition Ratings | |
|-----------------------|---|
| Excellent | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Good | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Fair | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life. |
| Poor | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| Failed | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required. |
| Not Applicable | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present. |

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

6. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall & Swift*, Bureau Veritas's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA. Soft costs are applied to each asset at a markup of 1.80 on the asset price. Soft cost markups include construction contingencies, construction management costs, design costs, regional cost factors, inflation to end of the current year, and general markup for unforeseen costs.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short Term window but will not be pushed 'irresponsibly' (too far) into the future.

7. Certification

Shelby County Board of Education (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Lucie E. Campbell Elementary School, 3232 Birchfield Drive, Memphis, Tennessee 38127, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: Patrick Fallon,
Project Manager

Reviewed by:



Al Diefert,
Technical Report Reviewer for
Andy Hupp,
Program Manager
Andy.Hupp@bureauveritas.com
800.733.0660 x7296632

8. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan
- Appendix C: Pre-Survey Questionnaire
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

Appendix A: **Photographic Record**

Photographic Overview



1 - FRONT ELEVATION



2 - LEFT ELEVATION



3 - REAR ELEVATION



4 - RIGHT ELEVATION



5 - MAIN ENTRANCE



6 - HALLWAYS

Photographic Overview



7 - PRE-K



8 - CLASSROOM




9 - CLASSROOM



10 - CLASSROOM



11 - LIBRARY



12 - CAFETERIA

Photographic Overview



13 - KITCHEN



14 - ROOFTOP HVAC



15 - PLAYGROUND



16 - PARKING LOT



17 - PARKING LOT



18 - LOADING DOCK

Appendix B:

Site Plan

Site Plan



| | | | |
|--|-----------------------|-------------------------------------|---|
|  BUREAU VERITAS | Project Number | Project Name |  |
| | 163745.23R000-051.354 | Lucie E. Campbell Elementary School | |
| Source | On-Site Date | | |
| Google | December 11-12, 2023 | | |

Appendix C: **Pre-Survey Questionnaire**

BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

| | |
|---|---|
| Building / Facility Name: | Lucie E. Campbell Elementary School |
| Name of person completing form: | Christopher Johnson |
| Title / Association w/ property: | Plant manager |
| Length of time associated w/ property: | 7 months |
| Date Completed: | 12/8/2023 |
| Phone Number: | |
| Method of Completion: | DURING - verbally completed during assessment |

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

| Data Overview | | Response | | |
|---------------|--|---|-----------|-----------------------|
| 1 | Year(s) constructed | Constructed 2003 | Renovated | |
| 2 | Building size in SF | 84,740 | SF | |
| 3 | Major Renovation/Rehabilitation | | Year | Additional Detail |
| | | Facade | | |
| | | Roof | | |
| | | Interiors | | |
| | | HVAC | 2023 | 2 old units remaining |
| | | Electrical | | |
| | | Site Pavement | | |
| | | Accessibility | | |
| 4 | List other significant capital improvements (focus on recent years; provide approximate date). | HVAC replacement in 2023 | | |
| 5 | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? | | | |
| 6 | Describe any on-going extremely problematic, historically chronic, or immediate facility needs. | New chiller not operating properly Boiler needs resetting frequently | | |

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

| Question | | Response | | | | Comments |
|----------|--|----------|----|-----|----|--|
| | | Yes | No | Unk | NA | |
| 7 | Are there any problems with foundations or structures, like excessive settlement? | | ✗ | | | |
| 8 | Are there any wall, window, basement or roof leaks? | | ✗ | | | |
| 9 | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints? | | ✗ | | | |
| 10 | Are your elevators unreliable, with frequent service calls? | ✗ | | | | Needs resetting often |
| 11 | Are there any plumbing leaks, water pressure, or clogging/backup issues? | ✗ | | | | In kitchen |
| 12 | Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service? | | ✗ | | | |
| 13 | Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas? | ✗ | | | | Pre-K hallway cold Admin hot |
| 14 | Is the electrical service outdated, undersized, or problematic? | | ✗ | | | |
| 15 | Are there any problems or inadequacies with exterior lighting? | ✗ | | | | Back road and parking lot need more lighting |
| 16 | Is site/parking drainage inadequate, with excessive ponding or other problems? | | ✗ | | | |
| 17 | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? | | ✗ | | | |
| 18 | ADA: Has an accessibility study been previously performed? If so, when? | | | | ✗ | |
| 19 | ADA: Have any ADA improvements been made to the property since original construction? Describe. | ✗ | | | | Door openers |
| 20 | ADA: Has building management reported any accessibility-based complaints or litigation? | | ✗ | | | |
| 21 | Are any areas of the property leased to outside occupants? | | ✗ | | | |



Signature of Assessor

Signature of POC

Appendix D: **Accessibility Review and Photos**

Visual Survey - 2010 ADA Standards for Accessible Design

Property Name: Lucie E. Campbell Elementary School

BV Project Number: 163745.23R000-051.354

Facility History & Interview

| Question | | Yes | No | Unk | Comments |
|----------|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------|
| 1 | Has an accessibility study been previously performed? If so, when? | | | <input checked="" type="checkbox"/> | |
| 2 | Have any ADA improvements been made to the property since original construction? Describe. | <input checked="" type="checkbox"/> | | | Door openers |
| 3 | Has building management reported any accessibility-based complaints or litigation? | | <input checked="" type="checkbox"/> | | |

Lucie E. Campbell Elementary School: Accessibility Issues

| Category | Major Issues (ADA study recommended) | Moderate Issues (ADA study recommended) | Minor Issues | None* |
|------------------------------|---|--|---------------------------|-------------------------------------|
| Parking | | | Worn parking lot markings | |
| Exterior Accessible Route | | | | <input checked="" type="checkbox"/> |
| Building Entrances | | | | <input checked="" type="checkbox"/> |
| Interior Accessible Route | | | | <input checked="" type="checkbox"/> |
| Elevators | | | | <input checked="" type="checkbox"/> |
| Public Restrooms | | | | <input checked="" type="checkbox"/> |
| Kitchens/Kitchenettes | | NA | | |
| Playgrounds & Swimming Pools | | NA | | |
| Other | | NA | | |

*be cognizant that if the "None" box is checked that does not guarantee full compliance; this study is limited in nature

Lucie E. Campbell Elementary School: Photographic Overview



OVERVIEW OF ACCESSIBLE PARKING AREA




CLOSE-UP OF STALL



ACCESSIBLE PATH



CURB CUT



MAIN ENTRANCE



SIGNAGE

Lucie E. Campbell Elementary School: Photographic Overview



ACCESSIBLE INTERIOR PATH



DOOR HARDWARE



LOBBY LOOKING AT CAB



IN-CAB CONTROLS



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

Appendix E: **Component Condition Report**

Component Condition Report | Lucie E. Campbell Elementary School

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------------|---------------------|-----------|--|------------|-----|---------|
| Structure | | | | | | |
| B1010 | Site | Fair | Loading Dock, Concrete | 650 SF | 55 | 7168584 |
| Facade | | | | | | |
| B2010 | Building Exterior | Fair | Exterior Walls, Concrete Block (CMU) | 13,800 SF | 30 | 7177829 |
| B2010 | Building Exterior | Fair | Exterior Walls, Brick | 23,000 SF | 30 | 7177830 |
| B2010 | Building exterior | Poor | Exterior Walls, Concrete Block (CMU), Repair/Repoint | 1,000 SF | 0 | 7177828 |
| B2020 | Building exterior | Fair | Screens & Shutters, Aluminum Window Screen, up to 15 SF | 135 | 3 | 7168618 |
| B2020 | Building Exterior | Fair | Window, Aluminum Double-Glazed, up to 15 SF | 135 | 10 | 7168675 |
| B2050 | Building Exterior | Fair | Exterior Door, Steel, Standard | 64 | 20 | 7168592 |
| B2080 | Site | Fair | Awning, Metal, per SF of awning, Refinish | 1,500 SF | 2 | 7177786 |
| Roofing | | | | | | |
| B3010 | Roof | Fair | Roofing, Single-Ply Membrane, TPO/PVC | 28,900 SF | 2 | 7168579 |
| B3010 | Roof | Fair | Roofing, Metal | 58,000 SF | 20 | 7168679 |
| Interiors | | | | | | |
| C1030 | Throughout building | Fair | Interior Door, Wood, Solid-Core | 145 | 20 | 7177205 |
| C1070 | Throughout building | Fair | Suspended Ceilings, Acoustical Tile (ACT) | 83,000 SF | 5 | 7177202 |
| C2010 | Throughout building | Fair | Wall Finishes, any surface, Prep & Paint | 169,500 SF | 2 | 7177200 |
| C2030 | Throughout building | Fair | Flooring, Vinyl Tile (VCT) | 78,900 SF | 2 | 7168609 |
| C2030 | Throughout building | Fair | Flooring, Carpet, Commercial Standard | 4,200 SF | 2 | 7168597 |
| Conveying | | | | | | |
| D1010 | Elevator | Fair | Passenger Elevator, Hydraulic, 2 Floors, Renovate | 1 | 10 | 7168624 |
| D1010 | Elevator | Fair | Elevator Cab Finishes, Standard | 1 | 2 | 7168582 |
| D1010 | Elevator | Fair | Elevator Controls, Automatic, 1 Car | 1 | 2 | 7168626 |
| Plumbing | | | | | | |
| D2010 | Riser Room | Fair | Backflow Preventer, Domestic Water | 1 | 10 | 7168611 |
| D2010 | Riser Room | Fair | Backflow Preventer, Domestic Water | 1 | 10 | 7168603 |
| D2010 | Restrooms | Fair | Toilet, Commercial Water Closet | 20 | 10 | 7177195 |
| D2010 | Kitchen | Fair | Sink/Lavatory, Commercial Kitchen, 3-Bowl | 2 | 10 | 7168585 |
| D2010 | Boiler room | Fair | Water Heater, Gas, Commercial (125 MBH) | 1 | 2 | 7168601 |
| D2010 | Boiler room | Fair | Backflow Preventer, Domestic Water | 1 | 10 | 7168656 |
| D2010 | Kitchen | Fair | Water Heater, Electric, Instant Hot | 1 | 2 | 7168638 |
| D2010 | Throughout building | Fair | Plumbing System, Supply & Sanitary, Medium Density (excludes fixtures) | 84,740 SF | 20 | 7177203 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Wall-Hung, Vitreous China | 30 | 10 | 7177198 |
| D2010 | Kitchen | Fair | Sink/Lavatory, Commercial Kitchen, 1-Bowl | 3 | 10 | 7168666 |
| D2010 | Restrooms | Fair | Urinal, Standard | 12 | 10 | 7177196 |
| D2010 | Boiler room | Fair | Water Heater, Gas, Commercial (600 MBH) | 1 | 2 | 7168687 |
| HVAC | | | | | | |
| D3020 | Boiler room | Fair | Boiler, Gas, HVAC | 1 | 10 | 7168615 |

Component Condition Report | Lucie E. Campbell Elementary School

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------------------|---------------------|-----------|---|-----------|-----|---------|
| D3020 | Riser Room | Fair | Unit Heater, Electric | 2 | 2 | 7168594 |
| D3020 | Boiler room | Fair | Boiler Supplemental Components, Expansion Tank | 1 | 20 | 7168690 |
| D3020 | Boiler room | Fair | Boiler Supplemental Components, Expansion Tank | 1 | 20 | 7168684 |
| D3020 | Boiler room | Fair | Unit Heater, Hydronic | 1 | 2 | 7168646 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump | 1 | 2 | 7168659 |
| D3030 | Electrical room | Fair | Split System, Fan Coil Unit, DX | 1 | 2 | 7168600 |
| D3030 | Site | Good | Chiller, Air-Cooled | 1 | 24 | 7168640 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-1] | 1 | 5 | 7168598 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-3] | 1 | 19 | 7168613 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-2] | 1 | 5 | 7168657 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Heating Water [P-8] | 1 | 5 | 7168583 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-4] | 1 | 19 | 7168614 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-1] | 1 | 19 | 7168645 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Heating Water [P-5] | 1 | 2 | 7168622 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Heating Water [P-6] | 1 | 2 | 7168672 |
| D3050 | Throughout building | Fair | HVAC System, Ductwork, High Density | 84,740 SF | 10 | 7177194 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted | 1 | 2 | 7168688 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-2] | 1 | 19 | 7168581 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Heating Water [P-7] | 1 | 5 | 7168686 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-3] | 1 | 5 | 7168616 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-4] | 1 | 5 | 7168652 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-6] | 1 | 19 | 7168658 |
| D3050 | Throughout building | Fair | HVAC System, Hydronic Piping, 2-Pipe | 84,740 SF | 20 | 7177199 |
| D3050 | Roof | Good | Air Handler, Exterior AHU [AHU-5] | 1 | 19 | 7168620 |
| D3050 | Roof | Fair | Make-Up Air Unit, MUA or MAU | 1 | 2 | 7168633 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 2 | 7168628 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 2 | 7168644 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 2 | 7168634 |
| Fire Protection | | | | | | |
| D4010 | Kitchen | Fair | Fire Suppression System, Commercial Kitchen, per LF of Hood | 5 LF | 2 | 7168610 |
| D4010 | Throughout building | Fair | Fire Suppression System, Existing Sprinkler Heads, by SF | 84,740 SF | 5 | 7168580 |
| D4030 | Throughout building | Fair | Fire Extinguisher, Type ABC, up to 20 LB | 16 | 2 | 7168649 |
| D4030 | Kitchen | Fair | Fire Extinguisher, Wet Chemical/CO2 | 1 | 2 | 7168665 |
| Electrical | | | | | | |
| D5020 | 218M | Fair | Distribution Panel, 277/480 V [HPE] | 1 | 10 | 7168667 |
| D5020 | Electrical room | Fair | Distribution Panel, 120/208 V [LPK] | 1 | 10 | 7168655 |
| D5020 | Site | Fair | Primary Transformer, Dry, Property-Owned | 1 | 10 | 7168647 |
| D5020 | 218M | Fair | Distribution Panel, 120/208 V [LPE] | 1 | 10 | 7168639 |
| D5020 | 100M | Fair | Secondary Transformer, Dry, Stepdown [Transformer LPC] | 1 | 10 | 7168671 |

Component Condition Report | Lucie E. Campbell Elementary School

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|--|---------------------|-----------|---|-----------|-----|---------|
| D5020 | Electrical room | Fair | Distribution Panel, 120/208 V [LPK] | 1 | 10 | 7168578 |
| D5020 | Electrical room | Fair | Secondary Transformer, Dry, Stepdown [Transformer LPK] | 1 | 10 | 7168669 |
| D5020 | Electrical room | Fair | Distribution Panel, 120/208 V [LPB] | 1 | 10 | 7168641 |
| D5020 | Electrical room | Fair | Secondary Transformer, Dry, Stepdown [TRANSFORMER LPB] | 1 | 10 | 7168604 |
| D5020 | Boiler room | Fair | Distribution Panel, 277/480 V [MPB] | 1 | 10 | 7168662 |
| D5020 | Elevator | Fair | Secondary Transformer, Dry, Stepdown [Elevator Transformer] | 1 | 10 | 7168668 |
| D5020 | Electrical room | Fair | Switchboard, 277/480 V [MSB] | 1 | 20 | 7168588 |
| D5020 | 100M | Fair | Distribution Panel, 120/208 V [LPC] | 1 | 10 | 7168605 |
| D5020 | Boiler room | Fair | Distribution Panel, 277/480 V [MPB] | 1 | 10 | 7168595 |
| D5020 | Electrical room | Fair | Distribution Panel, 120/208 V [LPB] | 1 | 10 | 7168636 |
| D5020 | 218M | Fair | Secondary Transformer, Dry, Stepdown [Transformer LPE] | 1 | 10 | 7168642 |
| D5020 | 100M | Fair | Distribution Panel, 277/480 V [HPC] | 1 | 10 | 7168590 |
| D5020 | Electrical room | Fair | Distribution Panel, 277/480 V [HPB] | 1 | 10 | 7168654 |
| D5030 | Throughout building | Fair | Electrical System, Wiring & Switches, Average or Low Density/Complexity | 84,740 SF | 20 | 7177197 |
| D5030 | Boiler room | Good | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-1] | 1 | 19 | 7168619 |
| D5030 | Boiler room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-8] | 1 | 2 | 7168648 |
| D5030 | Boiler room | Good | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-7] | 1 | 19 | 7168589 |
| D5030 | Boiler room | Good | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-4] | 1 | 19 | 7168670 |
| D5030 | Boiler room | Good | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-3] | 1 | 19 | 7168674 |
| D5030 | Boiler room | Good | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [P-2] | 1 | 19 | 7168685 |
| D5040 | Throughout building | Fair | Interior Lighting System, Full Upgrade, Medium Density & Standard Fixtures | 84,740 SF | 2 | 7177201 |
| Fire Alarm & Electronic Systems | | | | | | |
| D6030 | Cafeteria | Fair | Sound System, Theater/Auditorium/Church | 6,500 SF | 2 | 7177787 |
| D6060 | Throughout building | Fair | Intercom/PA System, Public Address Upgrade, Facility-Wide | 84,740 SF | 2 | 7168632 |
| D7010 | Throughout building | Fair | Intrusion Detection System, Full Alarm System Renovation/Upgrade, Upgrade/Install | 84,740 SF | 2 | 7168661 |
| D7030 | Throughout building | Fair | Security/Surveillance System, Full System Upgrade, High Density | 84,740 SF | 2 | 7168673 |
| D7050 | Office | Good | Fire Alarm Panel, Fully Addressable | 1 | 13 | 7168587 |
| D7050 | Throughout building | Fair | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 84,740 SF | 2 | 7168596 |
| D8010 | Boiler room | Fair | BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install | 84,740 SF | 2 | 7168612 |
| Equipment & Furnishings | | | | | | |
| E1030 | Kitchen | Fair | Foodservice Equipment, Garbage Disposal, 1 to 3 HP | 1 | 2 | 7168677 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Double | 1 | 5 | 7168617 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In | 1 | 2 | 7168637 |
| E1030 | Site | Fair | Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer | 1 | 2 | 7168591 |
| E1030 | Kitchen | Failed | Foodservice Equipment, Refrigerator, Undercounter 1-Door | 1 | 0 | 7168599 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 8 | 7168653 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer | 1 | 2 | 7177174 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steam Kettle | 1 | 2 | 7168678 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Range, 2-Burner | 1 | 2 | 7168623 |

Component Condition Report | Lucie E. Campbell Elementary School

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|---|-------------------|-----------|---|------------|-----|---------|
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer | 1 | 2 | 7177175 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Double | 1 | 6 | 7168606 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steamer, Freestanding | 1 | 2 | 7168680 |
| E1030 | Kitchen | Failed | Foodservice Equipment, Dishwasher Commercial | 1 | 0 | 7168650 |
| E1030 | Kitchen | Failed | Foodservice Equipment, Icemaker, Freestanding | 1 | 0 | 7168683 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Freezer | 1 | 2 | 7168651 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 2 | 7168664 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Refrigerator | 1 | 2 | 7168689 |
| E1030 | Site | Fair | Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer | 1 | 2 | 7168629 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steamer, Freestanding | 1 | 2 | 7168663 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Exhaust Hood, 8 to 10 LF | 2 | 9 | 7168660 |
| E1040 | Office | Fair | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted | 1 | 2 | 7168621 |
| E1070 | Cafeteria | Fair | Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour | 1,800 SF | 2 | 7168608 |
| Special Construction & Demo | | | | | | |
| F1020 | Site | Fair | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal | 100 SF | 10 | 7168631 |
| Pedestrian Plazas & Walkways | | | | | | |
| G2020 | Site | Poor | Parking Lots, Pavement, Asphalt, Mill & Overlay | 185,750 SF | 2 | 7168627 |
| Athletic, Recreational & Playfield Areas | | | | | | |
| G2050 | Site | Fair | Play Structure, Multipurpose, Small | 1 | 2 | 7168643 |
| G2050 | Site | Fair | Playfield Surfaces, Rubber, Interlocking Tiles | 2,300 SF | 2 | 7177789 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Large | 1 | 2 | 7168635 |
| G2050 | Site | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe | 45,000 SF | 2 | 7177790 |
| Sitework | | | | | | |
| G2060 | Site | Fair | Fences & Gates, Vehicle Gate, Chain Link Manual | 8 | 5 | 7168602 |
| G2060 | Site | Fair | Signage, Property, Monument, Replace/Install | 1 | 2 | 7168593 |
| G2060 | Site | Fair | Fences & Gates, Fence, Chain Link 8' | 1,985 LF | 20 | 7168607 |
| G2060 | Site | Fair | Fences & Gates, Fence, Chain Link 4' | 700 LF | 20 | 7168676 |
| G2060 | Building exterior | Fair | Signage, Property, Building-Mounted Individual Letters, Replace/Install | 50 | 2 | 7177827 |
| G2060 | Site | Fair | Park Bench, Metal Powder-Coated | 6 | 2 | 7177788 |
| G2060 | Site | Fair | Flagpole, Metal | 1 | 10 | 7168586 |
| G4050 | Site | Fair | Pole Light Fixture w/ Lamps, any type 30' High, w/ LED Replacement, Replace/Install | 14 | 2 | 7168630 |
| G4050 | Site | Poor | Site Walkway Fixture w/ Lamp, Bollard Style, Replace/Install | 13 | 1 | 7168625 |
| G4050 | Building exterior | Fair | Exterior Fixture w/ Lamp, any type, w/ LED Replacement | 8 | 2 | 7168682 |
| Utilities | | | | | | |
| G3010 | Site | Fair | Hydrant, Fire, Replace/Install | 2 | 10 | 7168681 |

Appendix F: **Replacement Reserves**

1/12/2024

| Location | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | Total Escalated Estimate |
|-------------------------------------|-----------------|----------------|--------------------|-----------------|------------|------------------|-----------------|-----------------|----------------|-----------------|--------------------|------------|------------------|-----------------|------------|-----------------|-----------------|--------------------|------------|------------------|--------------------|--------------------------|
| Lucie E. Campbell Elementary School | \$49,300 | \$9,373 | \$4,147,240 | \$44,255 | \$0 | \$515,496 | \$11,343 | \$24,905 | \$2,154 | \$11,743 | \$1,362,530 | \$0 | \$477,559 | \$81,504 | \$0 | \$26,953 | \$15,245 | \$2,154,693 | \$0 | \$805,736 | \$4,743,850 | \$14,483,879 |
| Grand Total | \$49,300 | \$9,373 | \$4,147,240 | \$44,255 | \$0 | \$515,496 | \$11,343 | \$24,905 | \$2,154 | \$11,743 | \$1,362,530 | \$0 | \$477,559 | \$81,504 | \$0 | \$26,953 | \$15,245 | \$2,154,693 | \$0 | \$805,736 | \$4,743,850 | \$14,483,879 |

| Uniform Code | Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost * | Subtotal | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | Deficiency Repair Estimate |
|--------------|----------------------|---------|---|----------------|------|-----|----------|------|-------------|-------------|----------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|-----------|----------------------------|
| B2010 | Building exterior | 7177828 | Exterior Walls, Concrete Block (CMU), Repair/Repoint | 0 | 0 | 0 | 1000 | SF | \$20.00 | \$20,000 | \$20,000 | | | | | | | | | | | | | | | | | | | | \$20,000 | |
| B2020 | Building Exterior | 7168675 | Window, Aluminum Double-Glazed, up to 15 SF, Replace | 30 | 20 | 10 | 135 | EA | \$650.00 | \$87,750 | | | | | | | | | | | | | | | | | | | | | \$87,750 | |
| B2020 | Building exterior | 7168618 | Screens & Shutters, Aluminum Window Screen, up to 15 SF, Replace | 10 | 7 | 3 | 135 | EA | \$300.00 | \$40,500 | | | | | | | | | | | | | | | | | | | | | \$81,000 | |
| B2050 | Building Exterior | 7168592 | Exterior Door, Steel, Standard, Replace | 40 | 20 | 20 | 64 | EA | \$600.00 | \$38,400 | | | | | | | | | | | | | | | | | | | | | \$38,400 | |
| B2080 | Site | 7177786 | Awning, Metal, per SF of awning, Refinish | 10 | 8 | 2 | 1500 | SF | \$2.50 | \$3,750 | | | | | | | | | | | | | | | | | | | | | \$7,500 | |
| B3010 | Roof | 7168679 | Roofing, Metal, Replace | 40 | 20 | 20 | 58000 | SF | \$13.00 | \$754,000 | | | | | | | | | | | | | | | | | | | | | \$754,000 | |
| B3010 | Roof | 7168579 | Roofing, Single-Ply Membrane, TPO/PVC, Replace | 20 | 18 | 2 | 28900 | SF | \$17.00 | \$491,300 | | | | | | | | | | | | | | | | | | | | | \$491,300 | |
| C1030 | Throughout building | 7177205 | Interior Door, Wood, Solid-Core, Replace | 40 | 20 | 20 | 145 | EA | \$700.00 | \$101,500 | | | | | | | | | | | | | | | | | | | | | \$101,500 | |
| C1070 | Throughout building | 7177202 | Suspended Ceilings, Acoustical Tile (ACT), Replace | 25 | 20 | 5 | 83000 | SF | \$3.50 | \$290,500 | | | | | | | | | | | | | | | | | | | | | \$290,500 | |
| C2010 | Throughout building | 7177200 | Wall Finishes, any surface, Prep & Paint | 10 | 8 | 2 | 169500 | SF | \$1.50 | \$254,250 | | | | | | | | | | | | | | | | | | | | | \$508,500 | |
| C2030 | Throughout building | 7168609 | Flooring, Vinyl Tile (VCT), Replace | 15 | 13 | 2 | 78900 | SF | \$5.00 | \$394,500 | | | | | | | | | | | | | | | | | | | | | \$789,000 | |
| C2030 | Throughout building | 7168597 | Flooring, Carpet, Commercial Standard, Replace | 10 | 8 | 2 | 4200 | SF | \$7.50 | \$31,500 | | | | | | | | | | | | | | | | | | | | | \$63,000 | |
| D1010 | Elevator | 7168582 | Elevator Cab Finishes, Standard, Replace | 15 | 13 | 2 | 1 | EA | \$9,000.00 | \$9,000 | | | | | | | | | | | | | | | | | | | | | \$18,000 | |
| D1010 | Elevator | 7168626 | Elevator Controls, Automatic, 1 Car, Replace | 20 | 18 | 2 | 1 | EA | \$5,000.00 | \$5,000 | | | | | | | | | | | | | | | | | | | | | \$5,000 | |
| D1010 | Elevator | 7168624 | Passenger Elevator, Hydraulic, 2 Floors, Renovate | 30 | 20 | 10 | 1 | EA | \$60,000.00 | \$60,000 | | | | | | | | | | | | | | | | | | | | | \$60,000 | |
| D2010 | Boiler room | 7168687 | Water Heater, Gas, Commercial (600 MBH), Replace | 20 | 18 | 2 | 1 | EA | \$32,000.00 | \$32,000 | | | | | | | | | | | | | | | | | | | | | \$32,000 | |
| D2010 | Boiler room | 7168601 | Water Heater, Gas, Commercial (125 MBH), Replace | 20 | 18 | 2 | 1 | EA | \$12,400.00 | \$12,400 | | | | | | | | | | | | | | | | | | | | | \$12,400 | |
| D2010 | Kitchen | 7168638 | Water Heater, Electric, Instant Hot, Replace | 15 | 13 | 2 | 1 | EA | \$1,500.00 | \$1,500 | | | | | | | | | | | | | | | | | | | | | \$3,000 | |
| D2010 | Boiler room | 7168656 | Backflow Preventer, Domestic Water, Replace | 30 | 20 | 10 | 1 | EA | \$3,200.00 | \$3,200 | | | | | | | | | | | | | | | | | | | | | \$3,200 | |
| D2010 | Riser Room | 7168611 | Backflow Preventer, Domestic Water, Replace | 30 | 20 | 10 | 1 | EA | \$3,200.00 | \$3,200 | | | | | | | | | | | | | | | | | | | | | \$3,200 | |
| D2010 | Riser Room | 7168603 | Backflow Preventer, Domestic Water, Replace | 30 | 20 | 10 | 1 | EA | \$3,200.00 | \$3,200 | | | | | | | | | | | | | | | | | | | | | \$3,200 | |
| D2010 | Throughout building | 7177203 | Plumbing System, Supply & Sanitary, Medium Density (excludes fixtures), Replace | 40 | 20 | 20 | 84740 | SF | \$11.00 | \$932,140 | | | | | | | | | | | | | | | | | | | | | \$932,140 | |
| D2010 | Restrooms | 7177195 | Toilet, Commercial Water Closet, Replace | 30 | 20 | 10 | 20 | EA | \$1,300.00 | \$26,000 | | | | | | | | | | | | | | | | | | | | | \$26,000 | |
| D2010 | Restrooms | 7177198 | Sink/Lavatory, Wall-Hung, Vitreous China, Replace | 30 | 20 | 10 | 30 | EA | \$1,500.00 | \$45,000 | | | | | | | | | | | | | | | | | | | | | \$45,000 | |
| D2010 | Restrooms | 7177196 | Urinal, Standard, Replace | 30 | 20 | 10 | 12 | EA | \$1,100.00 | \$13,200 | | | | | | | | | | | | | | | | | | | | | \$13,200 | |
| D2010 | Kitchen | 7168585 | Sink/Lavatory, Commercial Kitchen, 3-Bowl, Replace | 30 | 20 | 10 | 2 | EA | \$2,500.00 | \$5,000 | | | | | | | | | | | | | | | | | | | | | \$5,000 | |
| D2010 | Kitchen | 7168666 | Sink/Lavatory, Commercial Kitchen, 1-Bowl, Replace | 30 | 20 | 10 | 3 | EA | \$1,600.00 | \$4,800 | | | | | | | | | | | | | | | | | | | | | \$4,800 | |
| D3020 | Boiler room | 7168615 | Boiler, Gas, HVAC, Replace | 30 | 20 | 10 | 1 | EA | \$20,000.00 | \$20,000 | | | | | | | | | | | | | | | | | | | | | \$20,000 | |
| D3020 | Boiler room | 7168646 | Unit Heater, Hydronic, Replace | 20 | 18 | 2 | 1 | EA | \$2,100.00 | \$2,100</td | | | | | | | | | | | | | | | | | | | | | | |

1/12/2024

| Uniform Code | Location Description | Item ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost * | Subtotal | 2023 | | | | | | | | | | | | 2043 | | | | | | | | | | | | Deficiency Repair Estimate |
|--------------|----------------------|---------|---|----------------|------|-----|----------|------|-------------|-----------|------|------|---------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|---------|-----------|-------|--|----------------------------|
| | | | | | | | | | | | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | | | | | |
| D3060 | Roof | 7168628 | Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 18 | 2 | 1 | EA | \$2,400.00 | \$2,400 | | | \$2,400 | | | | | | | | | | | | | | | | | | | \$2,400 | | | |
| D3060 | Roof | 7168634 | Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 18 | 2 | 1 | EA | \$2,400.00 | \$2,400 | | | \$2,400 | | | | | | | | | | | | | | | | | | | \$2,400 | | | |
| D4010 | Throughout building | 7168580 | Fire Suppression System, Existing Sprinkler Heads, by SF, Replace | 25 | 20 | 5 | 84740 | SF | \$1.07 | \$90,672 | | | | | | | | | | | | | | | | | | | | | | \$90,672 | | | |
| D4010 | Kitchen | 7168610 | Fire Suppression System, Commercial Kitchen, per LF of Hood, Replace | 20 | 18 | 2 | 5 | LF | \$400.00 | \$2,000 | | | \$2,000 | | | | | | | | | | | | | | | | | | | \$2,000 | | | |
| D4030 | Throughout building | 7168649 | Fire Extinguisher, Type ABC, up to 20 LB, Replace | 10 | 8 | 2 | 16 | EA | \$150.00 | \$2,400 | | | \$2,400 | | | | | | | | | | | | | | | | | | | \$4,800 | | | |
| D4030 | Kitchen | 7168665 | Fire Extinguisher, Wet Chemical/CO2, Replace | 10 | 8 | 2 | 1 | EA | \$300.00 | \$300 | | | \$300 | | | | | | | | | | | | | | | | | | | | \$600 | | |
| D5020 | Site | 7168647 | Primary Transformer, Dry, Property-Owned, Replace | 30 | 20 | 10 | 1 | EA | \$87,000.00 | \$87,000 | | | | | | | | | | | | | | | | | | | | | | \$87,000 | | | |
| D5020 | Electrical room | 7168604 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 20 | 10 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | | | | | | | | | \$10,000 | | | |
| D5020 | Electrical room | 7168669 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 20 | 10 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | | | | | | | | | \$10,000 | | | |
| D5020 | Elevator | 7168668 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 20 | 10 | 1 | EA | \$6,700.00 | \$6,700 | | | | | | | | | | | | | | | | | | | | | | \$6,700 | | | |
| D5020 | 100M | 7168671 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 20 | 10 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | | | | | | | | | \$10,000 | | | |
| D5020 | 218M | 7168642 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 20 | 10 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | | | | | | | | | \$10,000 | | | |
| D5020 | Electrical room | 7168588 | Switchboard, 277/480 V, Replace | 40 | 20 | 20 | 1 | EA | \$75,000.00 | \$75,000 | | | | | | | | | | | | | | | | | | | | | | \$75,000 | | | |
| D5020 | Boiler room | 7168595 | Distribution Panel, 277/480 V, Replace | 30 | 20 | 10 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | |
| D5020 | Boiler room | 7168662 | Distribution Panel, 277/480 V, Replace | 30 | 20 | 10 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | |
| D5020 | Electrical room | 7168636 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | |
| D5020 | Electrical room | 7168641 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | | |
| D5020 | Electrical room | 7168654 | Distribution Panel, 277/480 V, Replace | 30 | 20 | 10 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | | |
| D5020 | Electrical room | 7168578 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | | |
| D5020 | Electrical room | 7168655 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | | |
| D5020 | 100M | 7168605 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | | |
| D5020 | 100M | 7168590 | Distribution Panel, 277/480 V, Replace | 30 | 20 | 10 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | | |
| D5020 | 218M | 7168639 | Distribution Panel, 120/208 V, Replace | 30 | 20 | 10 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | | | | | | | | \$6,000 | | | | |
| D5020 | 218M | 7168667 | Distribution Panel, 277/480 V, Replace | 30 | 20 | 10 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | | |
| D5030 | Throughout building | 7177197 | Electrical System, Wiring & Switches, Average or Low Density/Complexity, Replace | 40 | 20 | 20 | 84740 | SF | \$2.50 | \$211,850 | | | | | | | | | | | | | | | | | | | | | | \$211,850 | | | |
| D5030 | Boiler room | 7168648 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 18 | 2 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | |
| D5030 | Boiler room | 7168670 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 1 | 19 | 1 | EA | \$6,200.00 | \$6,200 | | | | | | | | | | | | | | | | | | | | | | \$6,200 | | | |
| D5030 | Boiler room | 7168619 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 1 | 19 | 1 | EA | \$6,200.00 | \$6,200 | | | | | | | | | | | | | | | | | | | | | \$6,200 | | | | |
| D5030 | Boiler room | 7168674 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 1 | 19 | 1 | EA | \$6,200.00 | \$6,200 | | | | | | | | | | | | | | | | | | | | | \$6,200 | | | | |
| D5030 | Boiler room | 7168685 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 1 | 19 | 1 | EA | \$6,200.00 | \$6,200 | | | | | | | | | | | | | | | | | | | | | \$6,200 | | | | |
| D5030 | Boiler room | 7168589 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 1 | 19 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | | | | | | | | \$5,300 | | | | |
| D5040 | Throughout building | 7177201 | Interior Lighting System, Full Upgrade, Medium Density & Standard Fixtures, Replace | 20 | 18 | 2</ | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

1/12/2024

| Uniform Code | Location Description | Item ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost * | Subtotal | 2023 | | | | | | | | | | | | 2043 | | | | | | | | | | | | Deficiency Repair Estimate |
|--|----------------------|---------|---|----------------|------|-----|----------|------|-------------|-----------|---------|-------------|-----------|---------|-----------|----------|----------|---------|----------|-------------|------|-----------|----------|------|----------|----------|-------------|------|-----------|-------------|--------------|----------|-----------|--|----------------------------|
| | | | | | | | | | | | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | | | | | |
| E1030 | Kitchen | 7168653 | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace | 15 | 7 | 8 | 1 | EA | \$1,700.00 | \$1,700 | | | | | | | | | \$1,700 | | | | | | | | | | | | \$1,700 | | | | |
| E1030 | Kitchen | 7168660 | Foodservice Equipment, Exhaust Hood, 8 to 10 LF, Replace | 15 | 6 | 9 | 2 | EA | \$4,500.00 | \$9,000 | | | | | | | | | | \$9,000 | | | | | | | | | | | | \$9,000 | | | |
| E1040 | Office | 7168621 | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted, Replace | 10 | 8 | 2 | 1 | EA | \$1,500.00 | \$1,500 | | | | \$1,500 | | | | | | | | | | | | | | | | | | | \$3,000 | | |
| E1070 | Cafeteria | 7168608 | Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour, Replace | 15 | 13 | 2 | 1800 | SF | \$15.00 | \$27,000 | | | \$27,000 | | | | | | | | | | | | | | | | | | | | \$54,000 | | |
| F1020 | Site | 7168631 | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal, Replace | 30 | 20 | 10 | 100 | SF | \$25.00 | \$2,500 | | | | | | | | | | | | | | | | | | | | | | | \$2,500 | | |
| G2020 | Site | 7168627 | Parking Lots, Pavement, Asphalt, Mill & Overlay | 25 | 23 | 2 | 185750 | SF | \$3.50 | \$650,125 | | | \$650,125 | | | | | | | | | | | | | | | | | | | | \$650,125 | | |
| G2050 | Site | 7177790 | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe | 5 | 3 | 2 | 45000 | SF | \$0.45 | \$20,250 | | | \$20,250 | | | | | | | | | | \$20,250 | | | | | | | | | | \$81,000 | | |
| G2050 | Site | 7177789 | Playfield Surfaces, Rubber, Interlocking Tiles, Replace | 15 | 13 | 2 | 2300 | SF | \$25.00 | \$57,500 | | | \$57,500 | | | | | | | | | | | | | | | | | | | | \$115,000 | | |
| G2050 | Site | 7168635 | Play Structure, Multipurpose, Large, Replace | 20 | 18 | 2 | 1 | EA | \$35,000.00 | \$35,000 | | | \$35,000 | | | | | | | | | | | | | | | | | | | | \$35,000 | | |
| G2050 | Site | 7168643 | Play Structure, Multipurpose, Small, Replace | 20 | 18 | 2 | 1 | EA | \$10,000.00 | \$10,000 | | | \$10,000 | | | | | | | | | | | | | | | | | | | | \$10,000 | | |
| G2060 | Site | 7177788 | Park Bench, Metal Powder-Coated, Replace | 20 | 18 | 2 | 6 | EA | \$700.00 | \$4,200 | | | \$4,200 | | | | | | | | | | | | | | | | | | | | \$4,200 | | |
| G2060 | Site | 7168602 | Fences & Gates, Vehicle Gate, Chain Link Manual, Replace | 25 | 20 | 5 | 8 | EA | \$1,700.00 | \$13,600 | | | | | | | | | | | | | | | | | | | | | | | \$13,600 | | |
| G2060 | Site | 7168607 | Fences & Gates, Fence, Chain Link 8', Replace | 40 | 20 | 20 | 1985 | LF | \$25.00 | \$49,625 | | | | | | | | | | | | | | | | | | | | | | | \$49,625 | | |
| G2060 | Site | 7168676 | Fences & Gates, Fence, Chain Link 4', Replace | 40 | 20 | 20 | 700 | LF | \$18.00 | \$12,600 | | | | | | | | | | | | | | | | | | | | | | | \$12,600 | | |
| G2060 | Building exterior | 7177827 | Signage, Property, Building-Mounted Individual Letters, Replace/Install | 20 | 18 | 2 | 50 | EA | \$150.00 | \$7,500 | | | \$7,500 | | | | | | | | | | | | | | | | | | | \$7,500 | | | |
| G2060 | Site | 7168593 | Signage, Property, Monument, Replace/Install | 20 | 18 | 2 | 1 | EA | \$3,000.00 | \$3,000 | | | \$3,000 | | | | | | | | | | | | | | | | | | | \$3,000 | | | |
| G2060 | Site | 7168586 | Flagpole, Metal, Replace | 30 | 20 | 10 | 1 | EA | \$2,500.00 | \$2,500 | | | | | | | | | | | | | | | | | | | | | | \$2,500 | | | |
| G3010 | Site | 7168681 | Hydrant, Fire, Replace/Install | 30 | 20 | 10 | 2 | EA | \$5,680.00 | \$11,360 | | | | | | | | | | | | | | | | | | | | | | \$11,360 | | | |
| G4050 | Site | 7168625 | Site Walkway Fixture w/ Lamp, Bollard Style, Replace/Install | 20 | 19 | 1 | 13 | EA | \$700.00 | \$9,100 | | | \$9,100 | | | | | | | | | | | | | | | | | | | \$9,100 | | | |
| G4050 | Site | 7168630 | Pole Light Fixture w/ Lamps, any type 30' High, w/ LED Replacement, Replace/Install | 20 | 18 | 2 | 14 | EA | \$6,800.00 | \$95,200 | | | \$95,200 | | | | | | | | | | | | | | | | | | | \$95,200 | | | |
| G4050 | Building exterior | 7168682 | Exterior Fixture w/ Lamp, any type, w/ LED Replacement, Replace | 20 | 18 | 2 | 8 | EA | \$600.00 | \$4,800 | | | \$4,800 | | | | | | | | | | | | | | | | | | | \$4,800 | | | |
| Totals, Unescalated | | | | | | | | | | \$49,300 | \$9,100 | \$3,909,171 | \$40,500 | \$0 | \$444,672 | \$9,500 | \$20,250 | \$1,700 | \$9,000 | \$1,013,850 | \$0 | \$334,950 | \$55,500 | \$0 | \$17,300 | \$9,500 | \$1,303,625 | \$0 | \$459,500 | \$2,626,555 | \$10,313,973 | | | | |
| Totals, Escalated (3.0% inflation, compounded annually) | | | | | | | | | | \$49,300 | \$9,373 | \$4,147,240 | \$44,255 | \$0 | \$515,496 | \$11,343 | \$24,905 | \$2,154 | \$11,743 | \$1,362,530 | \$0 | \$477,559 | \$81,504 | \$0 | \$26,953 | \$15,245 | \$2,154,693 | \$0 | \$805,736 | \$4,743,850 | \$14,483,879 | | | | |

Appendix G: **Equipment Inventory List**

D10 Conveying

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|---------------------------|---------------------|----------|-------------------------------------|-----------------|--------------------------------|--------------|--------------|--------------|---------|-----|
| 1 | 7168626 | D1010 | Elevator Controls | Automatic, 1 Car | | Lucie E. Campbell Elementary School | Elevator | Schindler Elevator Corporation | No dataplate | No dataplate | 2003 | | |
| 2 | 7168624 | D1010 | Passenger Elevator | Hydraulic, 2 Floors | 3500 LB | Lucie E. Campbell Elementary School | Elevator | Schindler Elevator Corporation | F0B 217Y | 7271C27G02 | 2003 | | |

D20 Plumbing

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|---------------------------|---------------------------|----------|-------------------------------------|-----------------|--------------|-------------|-----------------|--------------|---------|-----|
| 1 | 7168638 | D2010 | Water Heater | Electric, Instant Hot | 9.5 | Lucie E. Campbell Elementary School | Kitchen | Hatco | C-45 | 9483590324 | 2003 | | |
| 2 | 7168601 | D2010 | Water Heater | Gas, Commercial (125 MBH) | 75 GAL | Lucie E. Campbell Elementary School | Boiler room | Rheem / Ruud | G75-125 | URNG 1002G03131 | 2003 | | |
| 3 | 7168687 | D2010 | Water Heater | Gas, Commercial (600 MBH) | 250 GAL | Lucie E. Campbell Elementary School | Boiler room | Ventura | 72 V 250 | 1202109373 | 2003 | | |
| 4 | 7168611 | D2010 | Backflow Preventer | Domestic Water | 2 IN | Lucie E. Campbell Elementary School | Riser Room | Watts | 909 M10T RP | 388444 | 2003 | | |
| 5 | 7168603 | D2010 | Backflow Preventer | Domestic Water | 2 IN | Lucie E. Campbell Elementary School | Riser Room | Watts | 909 M10T RP | 387445 | 2003 | | |
| 6 | 7168656 | D2010 | Backflow Preventer | Domestic Water | 1.25 IN | Lucie E. Campbell Elementary School | Boiler room | Watts | 909 M10T RP | 387319 | 2003 | | |

D30 HVAC

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|---------------------------------------|---|-----------|-------------------------------------|-----------------|-------------------|-----------------|----------------|--------------|---------|-----|
| 1 | 7168615 | D3020 | Boiler | Gas, HVAC | 400 MBH | Lucie E. Campbell Elementary School | Boiler room | Cleaver-Brooks | FLX | BT 8365 | 2003 | | |
| 2 | 7168594 | D3020 | Unit Heater | Electric | 3 KW | Lucie E. Campbell Elementary School | Riser Room | TPI Corp | G3453T | No dataplate | 2003 | | 2 |
| 3 | 7168646 | D3020 | Unit Heater | Hydronic | 48 MBH | Lucie E. Campbell Elementary School | Boiler room | Sterling | Inaccessible | Inaccessible | 2003 | | |
| 4 | 7168690 | D3020 | Boiler Supplemental Components | Expansion Tank | 50 GAL | Lucie E. Campbell Elementary School | Boiler room | Inaccessible | Inaccessible | Inaccessible | 2003 | | |
| 5 | 7168684 | D3020 | Boiler Supplemental Components | Expansion Tank | 75 GAL | Lucie E. Campbell Elementary School | Boiler room | Inaccessible | Inaccessible | Inaccessible | 2003 | | |
| 6 | 7168640 | D3030 | Chiller | Air-Cooled | 226 TON | Lucie E. Campbell Elementary School | Site | Daikin Industries | AGZ226ETSEMNN0A | STNU220300113 | 2022 | | |
| 7 | 7168659 | D3030 | Split System | Condensing Unit/Heat Pump | 3 TON | Lucie E. Campbell Elementary School | Roof | York | H2RC036S06A | Illegible | 2003 | | |
| 8 | 7168600 | D3030 | Split System | Fan Coil Unit, DX | 3.5 TON | Lucie E. Campbell Elementary School | Electrical room | York | F2RP042H06B | (S)XGLS170707 | 2007 | | |
| 9 | 7168598 | D3050 | Pump [P-1] | Distribution, HVAC Chilled or Condenser Water | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | Bell & Gossett | e-1510 SSF | 0332904-01C22 | 2003 | | |
| 10 | 7168657 | D3050 | Pump [P-2] | Distribution, HVAC Chilled or Condenser Water | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | Bell & Gossett | e-1510 SSF | C332904-02022- | 2003 | | |
| 11 | 7168616 | D3050 | Pump [P-3] | Distribution, HVAC Chilled or Condenser Water | 15 HP | Lucie E. Campbell Elementary School | Boiler room | Bell & Gossett | 1510 SSF | PRD35218-2 G22 | 2003 | | |
| 12 | 7168652 | D3050 | Pump [P-4] | Distribution, HVAC Chilled or Condenser Water | 15 HP | Lucie E. Campbell Elementary School | Boiler room | Bell & Gossett | e1510 SSF | PRD35218-1 G22 | 2003 | | |
| 13 | 7168622 | D3050 | Pump [P-5] | Distribution, HVAC Heating Water | 1.5 HP | Lucie E. Campbell Elementary School | Boiler room | Armstrong | 3x3x6 4380 | C 473265 | 2003 | | |
| 14 | 7168672 | D3050 | Pump [P-6] | Distribution, HVAC Heating Water | 1.5 HP | Lucie E. Campbell Elementary School | Boiler room | Armstrong | 3X3X6 4380 | C 473266 | 2003 | | |
| 15 | 7168686 | D3050 | Pump [P-7] | Distribution, HVAC Heating Water | 5 HP | Lucie E. Campbell Elementary School | Boiler room | Armstrong | 3x2x8 4030 | C 474566 | 2003 | | |
| 16 | 7168583 | D3050 | Pump [P-8] | Distribution, HVAC Heating Water | 5 HP | Lucie E. Campbell Elementary School | Boiler room | Armstrong | 3x2x8 4030 | C 474493 | 2003 | | |
| 17 | 7168645 | D3050 | Air Handler [AHU-1] | Exterior AHU | 10000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH010GVCM | FB0U220600624 | 2022 | | |
| 18 | 7168581 | D3050 | Air Handler [AHU-2] | Exterior AHU | 7000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH007GVCM | FB0U220600625 | 2022 | | |
| 19 | 7168613 | D3050 | Air Handler [AHU-3] | Exterior AHU | 8000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH008GVCM | FB0U220600626 | 2022 | | |
| 20 | 7168614 | D3050 | Air Handler [AHU-4] | Exterior AHU | 28000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH028GVCH | FB0U220600627 | 2022 | | |
| 21 | 7168620 | D3050 | Air Handler [AHU-5] | Exterior AHU | 28000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH028GVCM | FB0U220600628 | 2022 | | |

| | | | | | | | | | | | |
|----|---------|-------|----------------------------|----------------------------------|----------|-------------------------------------|------|---------------------|-----------------|---------------|------|
| 22 | 7168658 | D3050 | Air Handler [AHU-6] | Exterior AHU | 6000 CFM | Lucie E. Campbell Elementary School | Roof | Daikin Industries | 0AH006GVCM | FB0U220600629 | 2022 |
| 23 | 7168633 | D3050 | Make-Up Air Unit | MUA or MAU | 2000 CFM | Lucie E. Campbell Elementary School | Roof | CaptiveAire Systems | Illegible | Illegible | 2003 |
| 24 | 7168688 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted | 15 TON | Lucie E. Campbell Elementary School | Roof | York | DM150N20P4AAA3A | NEMM047873 | 2004 |
| 25 | 7168628 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | 1500 CFM | Lucie E. Campbell Elementary School | Roof | Illegible | Illegible | Illegible | 2003 |
| 26 | 7168644 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | 1500 CFM | Lucie E. Campbell Elementary School | Roof | Greenheck | G-150-FM | 0CK 18781 | 2003 |
| 27 | 7168634 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | 1500 CFM | Lucie E. Campbell Elementary School | Roof | Illegible | Illegible | Illegible | 2003 |

D40 Fire Protection

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|--------------------------------|------------------------------------|----------|-------------------------------------|---------------------|--------------|-------|--------|--------------|---------|-----|
| 1 | 7168610 | D4010 | Fire Suppression System | Commercial Kitchen, per LF of Hood | | Lucie E. Campbell Elementary School | Kitchen | | | | 2003 | | 5 |
| 2 | 7168649 | D4030 | Fire Extinguisher | Type ABC, up to 20 LB | | Lucie E. Campbell Elementary School | Throughout building | | | | 2003 | | 16 |
| 3 | 7168665 | D4030 | Fire Extinguisher | Wet Chemical/CO2 | | Lucie E. Campbell Elementary School | Kitchen | | | | 2003 | | |

D50 Electrical

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|--|---------------------|----------|-------------------------------------|-----------------|-------------------|------------------------|----------------|--------------|---------|-----|
| 1 | 7168647 | D5020 | Primary Transformer | Dry, Property-Owned | 750 KVA | Lucie E. Campbell Elementary School | Site | Howard Industries | 9189-435280-695 | HI1247201601 | 2003 | | |
| 2 | 7168668 | D5020 | Secondary Transformer [Elevator Transformer] | Dry, Stepdown | 30 KVA | Lucie E. Campbell Elementary School | Elevator | Rex Manufacturing | No dataplate | No dataplate | 2003 | | |
| 3 | 7168604 | D5020 | Secondary Transformer [TRANSFORMER LPB] | Dry, Stepdown | 75 KVA | Lucie E. Campbell Elementary School | Electrical room | GE | 9T2303474G03 | 1475A382GBG109 | 2003 | | |
| 4 | 7168671 | D5020 | Secondary Transformer [Transformer LPC] | Dry, Stepdown | 75 KVA | Lucie E. Campbell Elementary School | 100M | GE | 9T2303474G03 | 14754382680199 | 2003 | | |
| 5 | 7168642 | D5020 | Secondary Transformer [Transformer LPE] | Dry, Stepdown | 75 KVA | Lucie E. Campbell Elementary School | 218M | GE | 9T2303474903 | 14754382686189 | 2003 | | |
| 6 | 7168669 | D5020 | Secondary Transformer [Transformer LPK] | Dry, Stepdown | 75 KVA | Lucie E. Campbell Elementary School | Electrical room | GE | 9T2303044 | 1475A382LBG001 | 2003 | | |
| 7 | 7168588 | D5020 | Switchboard [MSB] | 277/480 V | 1600 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | 40521513 | 17877145-1 | 2003 | | |
| 8 | 7168654 | D5020 | Distribution Panel [HPB] | 277/480 V | 400 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | ADF3424MBX | 162D097177 | 2003 | | |
| 9 | 7168590 | D5020 | Distribution Panel [HPC] | 277/480 V | 400 AMP | Lucie E. Campbell Elementary School | 100M | GE | ADF3244MBX | 162D097177 | 2003 | | |
| 10 | 7168667 | D5020 | Distribution Panel [HPE] | 277/480 V | 400 AMP | Lucie E. Campbell Elementary School | 218M | GE | ADF3244MBX | Illegible | 2003 | | |
| 11 | 7168641 | D5020 | Distribution Panel [LPB] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | AQF3424CBX | 1680097177 | 2003 | | |
| 12 | 7168636 | D5020 | Distribution Panel [LPB] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | AQF3424MTX | 1G2D097177 | 2003 | | |
| 13 | 7168605 | D5020 | Distribution Panel [LPC] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | 100M | GE | AQF 3424CBX | Illegible | 2003 | | |
| 14 | 7168639 | D5020 | Distribution Panel [LPE] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | 218M | GE | AQF3424CBX | 162D097177 | 2003 | | |
| 15 | 7168655 | D5020 | Distribution Panel [LPK] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | AQF 3424CBX | 1028017177 | 2003 | | |
| 16 | 7168578 | D5020 | Distribution Panel [LPK] | 120/208 V | 400 AMP | Lucie E. Campbell Elementary School | Electrical room | GE | AQF3424MTX | 162D097177 | 2003 | | |
| 17 | 7168662 | D5020 | Distribution Panel [MPB] | 277/480 V | 400 AMP | Lucie E. Campbell Elementary School | Boiler room | GE | 3424MTX | 162D097177 | 2003 | | |
| 18 | 7168595 | D5020 | Distribution Panel [MPB] | 277/480 V | 400 AMP | Lucie E. Campbell Elementary School | Boiler room | GE | ADF3424MBX | 162D097177 | 2003 | | |
| 19 | 7168619 | D5030 | Variable Frequency Drive [P-1] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | ABB | ACH580-VCR-012A-4+F267 | 2223306038 | 2022 | | |
| 20 | 7168685 | D5030 | Variable Frequency Drive [P-2] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | ABB | ACH580-VCR-012A-4+F267 | 2223306036 | 2022 | | |
| 21 | 7168674 | D5030 | Variable Frequency Drive [P-3] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | ABB | ACH580-VCR-023A-4+F267 | 2222703582 | 2022 | | |
| 22 | 7168670 | D5030 | Variable Frequency Drive [P-4] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | ABB | ACH580-VCR-023A-4+F267 | 2222703610 | 2022 | | |

| 23 | 7168589 | D5030 | Variable Frequency Drive [P-7] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | ABB | ACH550-UH-08A8-4 | 2114100075 | 2022 | | |
|---|---------|--------|--------------------------------|--|----------|-------------------------------------|-----------------|---------------------|------------------|---------------|--------------|---------|-----|
| 24 | 7168648 | D5030 | Variable Frequency Drive [P-8] | VFD, by HP of Motor | 7.5 HP | Lucie E. Campbell Elementary School | Boiler room | York | No dataplate | No dataplate | 2003 | | |
| D70 Electronic Safety & Security | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 7168587 | D7050 | Fire Alarm Panel | Fully Addressable | | Lucie E. Campbell Elementary School | Office | Honeywell | ONYX® NFS-320(E) | No dataplate | 2021 | | |
| E10 Equipment | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 7168617 | E1030 | Foodservice Equipment | Convection Oven, Double | | Lucie E. Campbell Elementary School | Kitchen | Cleveland | 22CET6.1 | 180423052539 | 2018 | | |
| 2 | 7168606 | E1030 | Foodservice Equipment | Convection Oven, Double | | Lucie E. Campbell Elementary School | Kitchen | Blodgett | BD0-100-G-ES | 101119C1016T | 2019 | | |
| 3 | 7168650 | E1030 | Foodservice Equipment | Dishwasher Commercial | | Lucie E. Campbell Elementary School | Kitchen | Hobart | CRS76A | 85-1037425 | 2003 | | |
| 4 | 7168660 | E1030 | Foodservice Equipment | Exhaust Hood, 8 to 10 LF | | Lucie E. Campbell Elementary School | Kitchen | CaptiveAire Systems | 5124 NFR | 175552 | 2017 | | 2 |
| 5 | 7168653 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Lucie E. Campbell Elementary School | Kitchen | FWE | UHS-12P | 165024803 | 2016 | | |
| 6 | 7168664 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Lucie E. Campbell Elementary School | Kitchen | FWE | MTU-12 | 102722304 | 2010 | | |
| 7 | 7168677 | E1030 | Foodservice Equipment | Garbage Disposal, 1 to 3 HP | | Lucie E. Campbell Elementary School | Kitchen | Hammerall | Inaccessible | Inaccessible | 2003 | | |
| 8 | 7168683 | E1030 | Foodservice Equipment | Ice maker, Freestanding | | Lucie E. Campbell Elementary School | Kitchen | Manitowoc | S570 | 030521893 | 2003 | | |
| 9 | 7168623 | E1030 | Foodservice Equipment | Range, 2-Burner | | Lucie E. Campbell Elementary School | Kitchen | Illegible | Inaccessible | Inaccessible | 2003 | | |
| 10 | 7168637 | E1030 | Foodservice Equipment | Refrigerator, 2-Door Reach-In | | Lucie E. Campbell Elementary School | Kitchen | McCall | 1020P01C | 5-790897 | 2008 | | |
| 11 | 7168599 | E1030 | Foodservice Equipment | Refrigerator, Undercounter 1-Door | | Lucie E. Campbell Elementary School | Kitchen | STANDEX | AR164WVS/0-A | 1811286164 | 2003 | | |
| 12 | 7168678 | E1030 | Foodservice Equipment | Steam Kettle | | Lucie E. Campbell Elementary School | Kitchen | Cleveland | KGL-40 | WT7414-00K-01 | 2003 | | |
| 13 | 7168680 | E1030 | Foodservice Equipment | Steamer, Freestanding | | Lucie E. Campbell Elementary School | Kitchen | Duke | DC-TEHF74PG M | 08152056 | 2015 | | |
| 14 | 7168663 | E1030 | Foodservice Equipment | Steamer, Freestanding | | Lucie E. Campbell Elementary School | Kitchen | Duke | DC-TEHF74PG M | 08152055 | 2015 | | |
| 15 | 7168591 | E1030 | Foodservice Equipment | Walk-In, Condenser for Refrigerator/Freezer | | Lucie E. Campbell Elementary School | Site | Heatcraft | Illegible | Illegible | 2003 | | |
| 16 | 7168629 | E1030 | Foodservice Equipment | Walk-In, Condenser for Refrigerator/Freezer | | Lucie E. Campbell Elementary School | Site | Heatcraft | BHT031L6CF | T03F 00363 | 2003 | | |
| 17 | 7177174 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refrigerator/Freezer | | Lucie E. Campbell Elementary School | Kitchen | Bohn | No dataplate | No dataplate | 2003 | | |
| 18 | 7177175 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refrigerator/Freezer | | Lucie E. Campbell Elementary School | Kitchen | BOHN | No dataplate | No dataplate | 2003 | | |
| 19 | 7168651 | E1030 | Foodservice Equipment | Walk-In, Freezer | | Lucie E. Campbell Elementary School | Kitchen | Kolpak | No dataplate | 03E0588 FRZ | 2003 | | |
| 20 | 7168689 | E1030 | Foodservice Equipment | Walk-In, Refrigerator | | Lucie E. Campbell Elementary School | Kitchen | Kolpak | No dataplate | 03E0568 CLR | 2003 | | |
| 21 | 7168621 | E1040 | Healthcare Equipment | Defibrillator (AED), Cabinet-Mounted | | Lucie E. Campbell Elementary School | Office | | | | 2003 | | |